

Basic Vehicle Condition Guide

Report ID: 17,693,349

Pass

Version: 2

Created: 09 Sep 2019


Fail

N/A

Make: Model: Hyundai Santa FE **Body Style:** SUV Year: 2004 Registration: CBP401 Reg Expiry: 09 Dec 2019 WoF Expiry: **Odometer: Good No:** 19 Sep 2020 204,282 Kms 17693349 VIN: KMHSB81DR4U70926 Next Service: 212600 Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Dents inner left rear wheel arch. Stone chips front screen. Dent left cant rail. Tailgate struts not working. No cargo blind. Steering wheel worn

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

<u>Interior Comments</u>				
Seats	Average			
Carpets	Average			
Panels	Good			
Dashboard	Good			

General Comments

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Brian Hill

Evidence of Cam Belt Replacement: No Kms:

	Engine						
~							
~							
~							
~							
Cooling System							
~							
~							
~							
Transmission							
~							
~							
		~					
~							
~							
~							
~							
depth	of tyre	s)					
4	.0	mm					
5.0		mm					
5.0		mm					
6.0		mm					
	Yes						
~							
~							
~							
Air Conditioning / Heater							
~							
v							
<i>v</i>							
V V V V V V V V V V V V V V V V V V V							
VVVVV							
V V V V V							
V V V V V							
VVVVV							
V V V V V							
V V V V V V							
V V V V V V V V V V V V V V V V V V V							
マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ て て て て て							
マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ て て て て て							
	5.	マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ マ					

I have read and understood this condition guide.

Name [.]			

02 Sep 2019

Date: