

Report ID: 17,695,739 Version: 3 28 Feb 2020 Created:

Signature:

Make:	Toyota	Model:	Hilux	Body Style:	Utility		Pass	Fail	N/A
Year:	2012	Registration:	GLY996	Reg Expiry:	18 Mar 2020	Engine			<u> </u>
WoF Expiry:	30 Oct 2020	Odometer:	228,871 Kms	Good No:	17695739	Oil level	~		
VIN:	MR0EZ12G904012489	Next Service:		Service History		Smoke & fumes	~		
			2			Performance	~		
	port is not a warranty					Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	P D			Radiator / Hoses (visual)	~		
S = scratch						Transmission	V		
D = dent SW 66						Operation	~		
R = rust				10	JHH	Noise	~		
PT = paint defects C = crack	ect			$ \cup$		Clutch	-		
P = pin dent	Ho	KI					~		
* = decals	PSC PSC			SIL-	FILTR	CV joints	~		
SC = stone chips						Wheel bearings	bearings 🖌		
W = significant scuffs						Brakes			
		Nata				Performance	~		<u> </u>
Body Insp	pection Comments	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake		(·	Ļ
Rear Taillights Broken , Fuel Release cable N/W , Aerial plug in roof ,						Tyres (lowest observed tread depth of tyres)			
						Left front	8	3	mm
						Right front	8	3	mm
						Left rear	7	7	mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Minor surfa	ce rust on under body o	of vehicle,				Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater			
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashte	Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
	_					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
/						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt Sat. Na									~
Evidence	of Cam Belt Replac	ement: Y	'es	Kms: 14	8,010	Reversing camera			~
Inspected by: Chris Buckley Date: 21 Jan 2020									

I have read and understood this condition guide.

Name: