


<b>Make:</b>	Toyota	<b>Model:</b>	Landcruiser Prado	<b>Body Style:</b>	SUV
<b>Year:</b>	2007	<b>Registration:</b>	EYL694	<b>Reg Expiry:</b>	12 Jul 2019
<b>WoF Expiry:</b>	06 May 2019	<b>Odometer:</b>	197,804 Kms	<b>Good No:</b>	17699753
<b>VIN:</b>	JTEBZ25J500122540	<b>Next Service:</b>	202000	<b>Service History:</b>	No

**Note: This report is not a warranty**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

**Key:**

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs


**Body Inspection Comments**

Note: some defects & blemishes may not be displayed in the diagram

Rear wiper not working. Spotlights on nudge bar not going and LH spotlight coming apart. LH spotlight in bumper has moisture. Stone guard damaged on bonnet. Damage on front bumper. Cracks in dash pad. Odour in car. Covers on both front seats coming off at rear.

Conditions During Body Inspection: Dry

**Under Carriage & Under Bonnet Inspection Comments**

Average condition.

**Interior Comments**

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

**General Comments**

Turbo has whine. Injector noise under acceleration, needs servicing.

Drives ok.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes Kms: 151,044

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	5	mm	
Right front	3	mm	
Left rear	3	mm	
Right rear	2	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)	✓		
Number of keys	1		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera			✓

Inspected by: Roger King

Date: 20 Nov 2018

I have read and understood this condition guide.

Name: .....

Signature: .....