

Report ID: 17,699,822 Version: 1 19 Nov 2018 Created:

Make:	Mazda	Model:	Bt-50	Body Style:	Utility		Pass	Fail	N/A
Year:	2015	Registration:	JLB181	Reg Expiry:	28 Jan 2019	Engine			
WoF Expiry:	02 Nov 2019	Odometer:	123,808 Kms	Good No:	17699822	Oil level	~		
VIN:	MM0UR0YF10049008	Next Service:	131271	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	lical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	charge.	Coolant condition	~		
			SC		S	Performance	~		
Key:		-0		-01-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			I
D = dent R = rust SC D D D D D D D D D D D D D D D D D D						Operation	~		
PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent	HIP				7414	CV joints	~		
* = decals SC 919 S						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P S P S						Performance	~		
Podylog	action Commonts	Note: son	ne defects & blemishes	s may not be disp	played in the diagram	Hand Brake	~		
Body Inspection Comments Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			es)
Wear on RF seat.						Left front	· · ·		
						Right front		3	mm
						Left rear		7	mm
Conditions During Body Inspection: Dry						Right rear		7	mm
						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Good cond	ition.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	I		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
Drives well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
	-		•			Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Inspected by: Roger King									
Inspected by: Roger King Date: 19 Nov 2018									

I have read and understood this condition guide.

Name:

Signature: