

Report ID: 17,700,354 Version: 1 12 Dec 2018 Created:

Make:	Mazda	Model:	323	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2002	Registration:	AST139	Reg Expiry:	17 Jul 2019	Engine	1	1	1
WoF Expiry:	20 Jul 2019	Odometer:	231,770 Kms	Good No:	17700354	Oil level	~		
VIN:	JM0BJ10M200215119	Next Service:	240600	Service Histor	y: No	Smoke & fumes	~		+
						Performance	~		+
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		+
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		+
Key:	SC W	-0	PT P SC SC		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent SSC DD SD						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch	~		
P = pin dent						CV joints	~		
*=decals SC QQ						Wheel bearings	~		
SC = stone chips						Brakes	V		L
W = significant scuffs S D SC W S PT SC S P SC W P SC						Performance	~		
		Note: son		may not be disp	laved in the diagram	Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	ofture	
Clearcoat coming off both mirrors. Stonechips on windscreen.						Tyres (lowest observed tread depth of tyres)			
						Left front		5	mm
						Right front		5	mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear		5	mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Cambelt has been changed but cannot read kms,so should be checked.						Suspension			
	oil seepage. Both rear s					Suspension performance	~		
-						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater	1		
Interior Comments						Operation	~		
Interior Comments Average						Electrical / Accessories			
Seats	Avelage					Head lights	~		ļ!
Carpets	Average					Tail lights	~		
	A					Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dashboa	rd Average					Wipers (front & rear)	~		
Dashboa						Window winder FL	~		
						Window winder FR	~		
	<u>Comments</u>					Window winder RL	~		
Clutch has wear.						Window winder RR	~		
Drives ok.						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
	-	- ·	•			Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: Y	′es	Kms: 1		Reversing camera			~
Inspected by: Roger King Date: 12 Dec 2018									
I have read and understood this condition guide. Name:									