

Report ID: 17,700,832 Version: 1 09 Jan 2019 Created:

Make:	Ford	Model:	Territory	Body Style:	SUV		Pass	Fail	N/A
Year:	2011	Registration:	GBD809	Reg Expiry:	30 Jun 2019	Engine			
WoF Expiry:	10 Oct 2019	Odometer:	146,901 Kms	Good No:	17700832	Oil level	~		
VIN:	6FPAAAJGATBS44356	Next Service:	157000	Service Histor	<b>y:</b> No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	DSC	-0	S P SC P SC	-161-	SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	s sc			TIN	E S	Operation	~		
R = rust PT = paint def				$\prod$		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HID				세비	CV joints	~		-
* = decals	sc 916			- Jul	ELL'S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC S SC S SC S SC S SC						Performance	~		
Dealerteen	<u></u>	Note: son	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	Tyres (lowest observed tread depth of tyres		
Stonechips on windscreen. Both rear windows not working from RF switch. Damage on back of LF seat.									mm
	-		-			Right front		3	mm
						Left rear	1		mm
Condition	as During Body Ins	noction:				Right rear		2	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Both front a	and LR tires have inside	edge wear. RR ti	re has outside edge we	ear.		Suspension performance	~		
		-	-			Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
	Average					Tail lights	V		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
	A					Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	r		
General C	<u>Comments</u>					Window winder RL	V		
Drives ok.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	V		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
							1	í	1
Inspected by: Roger King Date: 09 Jan 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....