

Report ID: 17,701,345 Version: 1 30 Jan 2019 Created:

Make:HoldenModel:EpicaBody Style:SedanYear:2010Registration:FJH360Reg Expiry:29 Jul 2019WoF Expiry:03 Dec 2019Odometer:206,978 KmsGood No:17701345VIN:KL3LA69LJAB047450Next Service:Service History:No		Pass	Fail	N/A
WoF Expiry: 03 Dec 2019 Odometer: 206,978 Kms Good No: 17701345	Engine			
	Oil level	~		
	Smoke & fumes	~		
	Performance	~		
Note: This report is not a warranty	Naina	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends	r I	v		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.	Coolant condition			
	Performance	~ ~		
Key: SC W PSC RPSC W S	Radiator / Hoses (visual)	-		
S = scratch	Transmission	~		
D=dent SDSCW				
R = rust	Operation	~		
PT = paint defect	Noise	~		
C = crack P = pin dent	Clutch			~
* = decals P SC P P	CV joints	~		
SC = stone chips	Wheel bearings	~		
W = significant scuffs	Brakes			
S P SC W S S PT SC P SC	Performance	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	Hand Brake	~		
Lights in mirrors taped over on both sides, cannot see if working. Paint coming off front edge of LR door.	Tyres (lowest observed tread	d depth	of tyre	es)
Surface rust on RR door window frame. Stonechips on windscreen. Damage on front bumper . Scratches on console. Has jack no tools. Surface rust on towbar.	Left front	5		mm
	Right front	4		mm
	Left rear	4		mm
Conditions During Body Inspection: Dry	Right rear	4		mm
·	Spare		Yes	
Under Carriage & Under Bonnet Inspection Comments	Suspension			
Pin hole in RF outer CV boot.	Suspension performance	~		
	Steering performance	~		
	Shock absorbers	~		
	Air Conditioning / Heater			
	Operation	~		
Interior Comments	Electrical / Accessories	11		1
Seats Average	Head lights	~		
	Tail lights	· ·		
Carpets Average	Indicators	~		
Panels Average	Dashboard warning lights	~		
	Wipers (front & rear)	~		
Dashboard	Window winder FL	~		
	Window winder FE	<i>v</i> <i>v</i>		
	Window winder FR			
General Comments		v		
<u>General Comments</u> Steering is heavy.	Window winder RR	v		
	Rear view mirrors	~		-
Steering is heavy.	Radio (basic test only)	~		-
Steering is heavy.		V		
Steering is heavy.	CD (basic test only)			
Steering is heavy. Drives ok.	Number of keys	2		
Steering is heavy.	Number of keys Central locking	2		
Steering is heavy. Drives ok. Road Conditions During Test Drive: Dry	Number of keys Central locking Remote locking	2		
Steering is heavy. Drives ok. Road Conditions During Test Drive: Dry Engine Timing Mechanism: Timing Chain	Number of keys Central locking	2		v
Steering is heavy. Drives ok. Road Conditions During Test Drive: Dry	Number of keys Central locking Remote locking	2		v v

I have read and understood this condition guide.

Name:

Signature: