

Report ID: 17,701,418 Version: 1 05 Feb 2019 Created:

Make:	Mitsubishi	Model:	Colt	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2004	Registration:		Reg Expiry:	24 Nov 2019	Engine			L
WoF Expiry:		Odometer:	147,637 Kms	Good No:	17701418	Oil level	~		
VIN:	JMAXSZ27A4Z000574	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I 1			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:	S D SC	-0	SP S		S D SC	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	ssc 6/6			The	SDC	Operation	~		
R = rust PT = paint defe				í In	THA	Noise	~		
C = crack					PT	Clutch			~
P = pin dent						CV joints	~		-
* = decals	PT SC PIE				ELIPE IS	Wheel bearings	~		
SC = stone chi	ps V	VA		1au	& <u> </u>	Brakes	•		
W = significan	t scuffs SC W	-	S PT SC S D P		IS SC	Performance	~		
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~		
	pection Comments				, .		Ť	oftyre	<u> </u>
LH indicator repeater lamp full of water, not going. Clearcoat is coming off vehicle. Damage on RR guard. Stonechips on windscreen. Damage on rear bumper. Corrosion on front wiper ams. Marks on front seats.						Tyres (lowest observed tread depth of tyres)Left front22mm			
Stoneemps	on windscreen. During	e onrear bumpe			on none seats.	Right front			mm
						Left rear	3		mm
							5 mm		
Conditions During Body Inspection: Dry						Right rear	5 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	s been changed but ca			dao waar oo bat	a front turos	Suspension			<u> </u>
	t on front suspension cr		Siloulu de checkeu. L	uge wear on bot	fillont tyles.	Suspension performance	~		
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
	Average					Electrical / Accessories			
Seats						Head lights	~		
Carpets	Average					Tail lights	~		
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		<u> </u>
	-					Window winder FL	~		<u> </u>
Concrel						Window winder FR	~		<u> </u>
Drives ok.	<u>Comments</u>					Window winder RL	~		<u> </u>
DIIVES UK.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry							~		
Engine Th	ning Machanian	Caralast	•			Remote locking	~		
Engine Timing Mechanism: Cambelt Evidence of Cam Belt Replacement: Yes Kms: 1									~
Evidence	or Cam Belt Replac	ement: Y	'es	Kms: 1		Reversing camera			~
Inspected by: Roger King Date: 05 Feb 2019									

I have read and understood this condition guide.

Name:

Signature: