

Report ID: 17,701,544 Version: 1 11 Feb 2019 Created:

Make:	Nissan	Model:	Murano	Body Style:	SUV		Pass	Fail	N/A
Year:	2007	Registration:	KMH962	Reg Expiry:	28 May 2019	Engine	1 433		
WoF Expiry:		Odometer:	102.856 Kms	Good No:	17701544	Oil level	~		<u> </u>
VIN:	7AT0DH74X17100265		102,030 Kills	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I II			Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	•		
	ical inspection prior to					Coolant condition	~		
		_				Performance	~		
Key:	SC	-0	S D P S SC		S D	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO		10c	X	Transmission	V		
D = dent				100	BIDS	Operation	~		T
R = rust				10		Noise	~		+
PT = paint def C = crack	ect 🛛			+	SC	Clutch	~		
C = Crack P = pin dent	Ho								~
* = decals	sc pp				Ell'As	CV joints	~		<u> </u>
SC = stone chi	ps V			10		Wheel bearings	~		
W = significant scuffs S SC S D S P S S						Brakes			
	550	N				Performance	~		<u> </u>
Body Ins	pection Comments	Note: som	ne defects & blemishe	s may not be disp	layed in the diagram	Hand Brake	<ul> <li>✓</li> </ul>		Ļ
Stonechips on windscreen. RH spotlight broken. RF park lamp not going. Trim on bottom of LF door						Tyres (lowest observed tread depth of tyres)			
damaged. Rear bumper not fitting correctly RHS. RF seat has wear and is not secure. Key remote is damaged.						Left front		3	mm
		,	5			Right front		3	mm
						Left rear		4	mm
Conditions During Body Inspection: Dry						Right rear	4 mm		
Under Carriage & Under Report Inspection Comments						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments Cracking on sidewalls of both front tyres. Engine has oil seepage.						Suspension			
Cracking or	i sidewalls of both front	tyres. Engine ha	as oll seepage.			Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation	~		
Average						Electrical / Accessories		1	
Seats	, weitige					Head lights	~		<u> </u>
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		<u> </u>
Dashboa	rd Average					Wipers (front & rear)	~		
						Window winder FL	~		
Concrol	Comments					Window winder FR	~		<u> </u>
	<u>.omments</u> needs adjustment.					Window winder RL	~		<u> </u>
	needs adjustitient.					Window winder RR	~		<u> </u>
Drives ok.						Rear view mirrors	~		
						Radio (basic test only)	~		<u> </u>
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	t Drive:	Dry			Central locking	~		<u> </u>
F		<b>T</b> ''	Ch a lia			Remote locking		~	
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~		
Increast-	d by Bogor King					Date: 11 Feb 20	10		
Inspecte	d by: Roger King					Date: 11 Feb 20	לו		
I have read	and understood th	is condition g	juide. Name:			Signature:			