

Signature:

Make:	Subaru	Model:	Forester	Body Style:	SUV		Pass	Fail N/A
Year:	2005		GKF418	Reg Expiry:	01 Jul 2019	Engine		
	05 Aug 2020	Odometer:	175,444 Kms	Good No:	17702735	Oil level	~	
VIN:	7AT0GF17X12086977	Next Service:		Service Histor		Smoke & fumes	~	
						Performance	~	
	port is not a warranty		C 1 1			Noise	~	
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition		
						Performance	~	
Key:	S SC	-0	S SC S SC		S P SC	Radiator / Hoses (visual)	~	
S = scratch						Transmission		
D = dent	S D PT SC			The	S D PT	Operation	~	
R = rust PT = paint defe				í In	JHIH	Noise	~	
C = crack					SC	Clutch		~
P = pin dent						CV joints	~	
* = decals SPSC OID SDP						Wheel bearings	~	
SC = stone chips						Brakes		
W = significan	t scuffs S SC W	-ve	S P S D P S		SP	Performance	~	
Dedulmen		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~	
Body Inspection Comments					Tyres (lowest observed tread depth of tyres)			
Rear bumper damaged. Stonechips on windscreen. RR widow noisy when operated. Scratches on trim in cargo area.					Left front	2 mm		
Wear on RF seatbelt.						Right front	2	mm
						Left rear	3	mm
Conditions During Body Inspection: Wet					Right rear	3 mm		
Conditions During body inspection. Wet					Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments					Suspension			
Inner edge	wear on both front tyre	s. Rear disc pads	low.			Suspension performance	~	
						Steering performance	~	
Shock absorbers							~	
						Air Conditioning / Heater	II	
						Operation	~	
Interior Comments						Electrical / Accessories		
Seats	Average					Head lights	~	
	Average					Tail lights	~	
Carpets	, we age					Indicators	~	
Panels	Average					Dashboard warning lights	~	
	, Average					Wipers (front & rear)	~	
Dashboa	rd ///elage					Window winder FL	~	
	·					Window winder FR	~	
General Comments						Window winder RL	~	
Automatic transmission has firm shifts, may need service.					Window winder RR	~		
Drives ok.						Rear view mirrors	~	
						Radio (basic test only)	~	
						CD (basic test only)	~	
						Number of keys	2	
Road Conditions During Test Drive: Dry						Central locking	~	
	-					Remote locking	~	
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)		~
Evidence	of Cam Belt Replac	ement: Y	es	Kms: 11	3,269	Reversing camera		~
Inspected by: Roger King Date: 06 Aug 2019								

I have read and understood this condition guide.

Name: