

I have read and understood this condition guide.

Report ID: 17,703,745 Version: 1 09 Jul 2019 Created:

Signature:

Make:	Nissan	Model:	Pulsar	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2015	Registration:	JDH585	Reg Expiry:	25 Aug 2019	Engine			1
WoF Expiry:	16 May 2020	Odometer:	55,114 Kms	Good No:	17703745	Oil level	~		
VIN:	MNTFAAC12A000775	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismontled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SSC	-0	SP S	-161-	sc	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent						Operation 🖌			
R = rust PT = paint defe				\prod	JHIH	Noise	~		
C = crack				$+ \mathbf{\nabla}$	SC	Clutch	•		~
P = pin dent						CV joints	~		•
* = decals	SPSC 916			The	ELTP S	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs SC S S S SC						Performance	~		
		Note [,] som	e defects & blemishes	may not be disr		Hand Brake	~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							-	oftyre))
Stonechips on windscreen. Mark on roof lining by RH sunvisor. Wear on RF seat.						Tyres (lowest observed tread depth of tyres) Left front 2 mm			mm
Mark on root mining by net survisor, weat on ne seat.						Right front			
						Left rear	3		mm
							6		mm
Conditions During Body Inspection: Dry								mm	
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
Good condition.						Suspension			
Good cond	ition.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	0000					Head lights	~		
Carpets	Good					Tail lights	~		
	Good					Indicators	~		
Panels	9000					Dashboard warning lights	~		
Dashboa	Good Good					Wipers (front & rear)	~		
						Window winder FL	~		
Canada						Window winder FR	~		
<u>General Comments</u> Drives well.						Window winder RL	~		
Drives well.						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry						Central locking	~		
		·				Remote locking	<		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Roger King Date: 09 Jul 2019									

Name: