

Report ID: 17,704,341 Version: 1 Created: 07 Nov 2018

Make:	Holden	Model:	Combo	Body Style:	Van		Pass	Fail	N/A
Year:	2006	Registration:	DDZ836	Reg Expiry:	19 Aug 2019	Engine			1
	13 Apr 2019	Odometer:	53,758 Kms	Good No:	17704341	Oil level	~		
VIN:	W0L0XCF2563025435	Next Service:		Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or						Noise	~		
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition	~		
						Performance	~		
Key:		-0	S PT			Radiator / Hoses (visual)	~		
S = scratch						Transmission	•		
						Operation	~		
R = rust						Noise	~		
PT = paint defect C = crack						Clutch	~		
P = pin dent						CV joints	~		
* = decals D SC D D						Wheel bearings	-		
SC = stone chips						Brakes	~		
W = significant scuffs W S D									
Note: come defects % blamiches may not be displayed in the diagram							~		
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake			
Windscreen chips						Tyres (lowest observed tread depth of tyres)			
						Left front	,		mm
						Right front	7		mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6 m		mm
Under Carriage & Under Bonnet Inspection Comments						Spare Yes			
						Suspension			
Right rear s	hock absorber worn					Suspension performance	~		
						Steering performance	~		
						Shock absorbers		~	
						Air Conditioning / Heater			
						Operation	~		
Interior Comments Some marks						Electrical / Accessories			
Seats	some man	KS				Head lights	~		
Carpets	Average					Tail lights	~		
						Indicators	~		
Panels	Average					Dashboard warning lights	~		
Dealahaa	Good					Wipers (front & rear)	~		
Dashboa	ira					Window winder FL	~		
	_					Window winder FR	~		
<u>General Comments</u>						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys			1
Road Conditions During Test Drive: Wet						Central locking	~		
						Remote locking			~
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
							1		1
Inspected by: John Lindsay Date: 07 Nov 2018									
I have read and understood this condition guide. Name:									