

Report ID: 17,704,727 Version: 3 01 Feb 2019 Created:

Make:	Suzuki	Model:	Swift	Body Style:	Hatchback	7		Pass	Fail	N/A	
Year:	2015	<b>Registration:</b>	JAZ235	<b>Reg Expiry:</b>	30 Mar 2019	En	igine				
WoF Expiry:	15 Feb 2020	Odometer:	29,395 Kms	Good No:	17704727		Dil level	~			
VIN:	JSAFZC82S00314272	Next Service:	39000	Service Histor	<b>y:</b> Yes		Smoke & fumes	~			
						5	Performance	~			
Note: This report is not a warranty This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or							Noise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends							Cooling System				
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Coolant condition	~			
						┓┝╻	Performance	~			
Key:							Radiator / Hoses (visual)	~			
S = scratch						Tr	Transmission				
D = dent R = rust PT = paint defect							Operation	~			
							Noise	~			
						] -	Clutch	•		~	
P = pin dent							CV joints	~			
* = decals P 999 SD							Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SD W SD SP W D							Performance	~			
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram		Hand Brake	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram							res (lowest observed tread	•	oftvre		
Hole in front bumper Left front roof rack cover missing						ΙĽ	Left front 4.0 mm				
Rear bumper alignment right side							Right front			mm	
Right side sill scratched Right rear tyre outer edge wear							_eft rear	4		mm	
							Right rear			 mm	
Conditions During Body Inspection: Dry							-				
Under Carriage & Under Bonnet Inspection Comments							Spare Yes Suspension				
							Suspension performance	~			
							Steering performance				
							Shock absorbers	ン ン			
								V			
						┛┣╴	Air Conditioning / Heater				
Interior Comments							Operation V				
Average							Electrical / Accessories Head lights				
Seats							-	~			
Carpets	Average						Fail lights ndicators	<b>v</b>			
	Average							~			
Panels							Dashboard warning lights	~			
Dashboa	rd Average						Nipers (front & rear)	~			
							Window winder FL	~			
General Comments							Window winder FR	~			
							Window winder RL	~			
							Window winder RR	•			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	•			
						_  -	Number of keys	2			
Road Conditions During Test Drive: Dry							Central locking	~			
Engine Tir	ning Mechanism:	Timing (	Chain				Remote locking	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Sat. Nav. (basic test only)			~	
							Reversing camera			~	
Inspected by: John Lindsay Date: 25 Jan 2019											

I have read and understood this condition guide.

Name: .....

Signature: .....