

Report ID: 17,704,855 Version: 2 07 Feb 2019 Created:

| Make: | Suzuki | Model: | Swift | Body Style: | Hatchback | | Pass | Fail | N/A |
|--|---|-----------------|------------------------|--|----------------------|--|-------|------|-----|
| Year: | 2015Registration:JAZ234Reg Expiry:30 Mar 2019 | | | | Engine | | | | |
| WoF Expiry: | 14 Feb 2020 | Odometer: | 39,658 Kms | Good No: | 17704855 | Oil level | ~ | | |
| VIN: | JSAFZC82S00315132 | Next Service: | 50000 | Service Histor | y: Yes | Smoke & fumes | ~ | | |
| | | | | | | Performance | V | | |
| | port is not a warranty a quide only. Conside | eration is made | for age and mileage. | Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a run mechan | ical inspection prior to | purchase and tr | lis can be arranged to | r an additional C | .narge. | Coolant condition | ~ | | |
| | | | S | | | Performance | ~ | | |
| Key: | | = | | 5(0)- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| R = rust | | | | 10 | HILS | Operation | ~ | | |
| PT = paint defe | ect NP | | | | | Noise | ~ | | |
| C = crack | | | | The second secon | | Clutch | | | ~ |
| P = pin dent | HP | | | | 2416 | CV joints | ~ | | |
| * = decals | | | | | | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| in significant | S W | | S D S D W | W | DW | Performance | ~ | | |
| Body Insp | ection Comments | Note: som | ne defects & blemishes | may not be disp | layed in the diagram | Hand Brake | ~ | | |
| Left side wing mirror indicator cover broken | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| Left rear roof rack cover missing Front bumper rubber spoiler loose | | | | | | Left front | 5.0 | | mm |
| Front bump | er rubber spoller loose | | | | | Right front | 4 | .0 | mm |
| | | | | | | Left rear | 6 | .0 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 6.0 m | | mm |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments Suspension - Suspension performance | | | | | | Suspension | | | |
| | | | | | | ~ | | | |
| Steering performance | | | | | | | ~ | | |
| Shock absorbers | | | | | | | ~ | | |
| Air Condi | | | | | | | | | |
| Operation | | | | | | | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Marks on s | seats | | | | Head lights | ~ | | |
| Carpets | Average | | | | | Tail lights | ~ | | |
| | | | | | | Indicators | | ~ | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| Dashboa | rd Scratches | on dashboard | | | | Wipers (front & rear) | ~ | | |
| Dastibua | iu . | | | | | Window winder FL | ~ | | |
| | •• | | | | | Window winder FR | ~ | | |
| <u>General Comments</u> | | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | or Cam Beit Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| Inspected by: John Lindsay Date: 29 Jan 2019 | | | | | | | | | |

I have read and understood this condition guide.

Name:

Signature: