

Report ID: 17,705,841 Version: 1 14 Feb 2019 Created:

Make:	Hyundai	Model:	Accent	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2013	Registration:	GSU263	Reg Expiry:	17 Feb 2020	Engine			
WoF Expiry:	17 Jan 2020	Odometer:	123,995 Kms	Good No:	17705841	Oil level	~		
VIN:	KMHCT51UMCU0802(	Next Service:	133000	Service History	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	V		
	port is not a warranty	aration is made	for ago and milaago	Darts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	s s	-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	PT SC W			The	S D PT	Operation	~		
R = rust PT = paint defe				$\prod$		Noise	~		
C = crack					S R SC	Clutch			~
P = pin dent	HID				74 <u>11</u>	CV joints	~		
* = decals SC 99						Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs W		SD SP			Performance	V		
Body Incr	oction Commonts	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	V		
Body Inspection Comments Aerial mount on roof damaged						Tyres (lowest observed tread depth of tyres)			es)
Aenal mount of roof damaged					Left front 5 mn			mm	
						Right front	e	5	mm
						Left rear		5	mm
Conditions During Body Inspection: Dry						Right rear	6	6 mm	
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	r		
						Shock absorbers	~		
						Air Conditioning / Heater	1		1
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Hole in dri	vers seat, stains o	on rear seat			Head lights	~		
	Drivers car	rpet worn				Tail lights	~		
Carpets		permon				Indicators	~		
Panels	Scratches	on rear panels				Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: John Lindsay Date: 14 Feb 2019									

I have read and understood this condition guide.

Name: .....

Signature: .....