

Basic Vehicle Condition Guide

Report ID: 17,705,962


Version: 1

Created: 16 Feb 2019

Make: Model: Hyundai 140 **Body Style:** Sedan Year: 2014 Registration: HPA318 Reg Expiry: 28 Feb 2019 Good No: WoF Expiry: **Odometer:** 13 Jul 2019 104,616 Kms 17705962 VIN: KMHLB41UMEU05769 Next Service: 116000' **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Interior Comments				
Seats	Good			
Carpets	Good			
Panels	Good			
Dashboard	Good			

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

16 Feb 2019 Inspected by: John Lindsay Date:

Name:

	Pass	Fail	N/A
Engine			
Oil level	~		
Smoke & fumes	\(\times \)		
Performance	~		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	<i>V V</i>		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	es)
Left front	į	5	mm
Right front	(5	mm
Left rear	4	4	mm
Right rear	4		mm
Spare		Yes	
Suspension	•		
Suspension performance	~		
Steering performance	<i>V</i>		
Shock absorbers	~		
Air Conditioning / Heater			•
Operation	~		
Electrical / Accessories			•
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \)		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	VVV		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2		•
Central locking			~
Remote locking	~		
Sat. Nav. (basic test only)			~
Reversing camera	~		

Signature: