

Basic Vehicle Condition Guide

Report ID: 17,707,092

Pass

~

/

V

1

J

Tyres (lowest observed tread depth of tyres)

Version:

Engine

Oil level

Noise

Smoke & fumes

Performance

Cooling System

Transmission

Operation

Noise

Clutch

Brakes

CV joints

Wheel bearings

Performance

Hand Brake

Left front

Right front

Left rear

Right rear

Suspension

Operation

Head lights
Tail lights
Indicators

Suspension performance

Steering performance

Air Conditioning / Heater

Electrical / Accessories

Dashboard warning lights

Wipers (front & rear)

Window winder FL
Window winder FR

Window winder RL

Window winder RR
Rear view mirrors

Radio (basic test only)

CD (basic test only)

Number of keys

Central locking

Remote locking

Reversing camera

Sat. Nav. (basic test only)

Shock absorbers

Spare

Coolant condition
Performance

Radiator / Hoses (visual)

Created: 11 Mar 2019

Fail

1

N/A

mm

mm

mm

 mm

3

2

3

1

/

/

/

1

1


1

Yes

Make: Mitsubishi Model: Legnum **Body Style:** Wagon Year: 1997 Registration: CSG452 **Reg Expiry:** 13 Dec 2019 WoF Expiry: **Odometer:** 07 Jun 2019 224,333 Kms **Good No:** 17707092 VIN: 7A8CJ300705100481 **Next Service:** 221270 **Service History:** No

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Left front monsoon missing Chips windscreen

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Left front kick panel missing Front tyres outer edge wear Oil leak Rear right tyre outer edge wear

Left rear tyre outer and inner edge wear

Right tie rod leaking

Interior Comments					
-	Seats	driver seat worn			
	Carpets	Average			
	Panels	Average			

Dashboard shifter surround doesn't fit

General Comments

Engine not idling

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No.

Evidence of Cam Belt Replacement: No Kms:

Date: 11 Mar 2019

ame:	 Signature:	

l have read	ممط	undorct	and this	condition	مينظم
i nave read	and	underst	ood this	condition	allide

Kyle Mills-Brown