

Report ID: 17,708,787 Version: 2 21 May 2019 Created:

| Make: | Ford | Model: | Falcon | Body Style: | Sedan | | Pass | Fail | N/A |
|--|--|----------------------|------------------------|---------------------|-----------------------|--|------|------|----------|
| Year: | 2003 | Registration: | GCJ861 | Reg Expiry: | 18 Apr 2019 | Engine | 1 | | |
| WoF Expiry: | 19 Jan 2019 | Odometer: | 171,649 Kms | Good No: | 17708787 | Oil level | ~ | | |
| VIN: | 6FPAAAJGSW3M5561 | Next Service: | | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty a quide only. Consid | | for age and mileage | . Parts have not | been dismantled or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | lical inspection prior to | purcnase and t | his can be arranged fo | or an additional of | narge. | Coolant condition | ~ | | |
| | S PT W | | S D PT S D | | S | Performance | ~ | | |
| Key: | | -0 | | 500- | | Radiator / Hoses (visual) | ~ | | |
| S = scratch D = dent | | | | | | Transmission | | | |
| D = dent R = rust | S PT SC W | | | 710 | HIVSW | Operation | ~ | | |
| PT = paint defe | ect NP | | | | 101h | Noise | ~ | | |
| C = crack | | | | | R PT SC | Clutch | | | ~ |
| P = pin dent | SRPTSC DE | | | | 74116 | CV joints | ~ | | |
| * = decals | | | | To . | ED SPT | Wheel bearings | ~ | | |
| SC = stone chips W = significant scuffs | | | | | | Brakes | | | |
| | S PT W | | S D PT S D | | S | Performance | ~ | | |
| Body Incr | pection Comments | Note: son | ne defects & blemishes | s may not be disp | blayed in the diagram | Hand Brake | ~ | | |
| Body Inspection Comments | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | 4 | 1 | mm |
| | | | | | | Right front | 5 | 5 | mm |
| | | | | | | Left rear | Ľ. | 5 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 4 | 4 mm | |
| | | | | | | Spare | Yes | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Suspension | | | |
| Driver seat holes | | | | | | Suspension performance | ~ | | |
| Front tyres inner and outer edge wear Oil leak engine | | | | | | Steering performance | ~ | | |
| Underbody oxidisation | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | 1 | | |
| L | | | | | | Operation | ~ | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | driver sea | t surround cracke | ed and front seats wor | n | | Head lights | ~ | | |
| | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | ra | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | | |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| | | | • | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | | | ~ |
| Evidence | of Cam Belt Replac | ement: N | lot Applicable | Kms: | | Reversing camera | | | ~ |
| la a | | | | | | D-4- 01 M- 00 | 10 | | |
| Inspected | d by: Kyle Mills-Brow | | | | | Date: 21 May 20 | 717 | | |

I have read and understood this condition guide.

Name:

Signature: