

Report ID: 17,709,526 Version: 1 Created: 25 Oct 2018

Make:	Skoda	Model:	Octavia	Body Style:	Sedan		Pass	Fail	N/A
Year:	2011	<b>Registration:</b>	FYC170	Reg Expiry:	15 Aug 2019	Engine	1	I	1
WoF Expiry:	14 Sep 2019	Odometer:	168,283 Kms	Good No:	17709526	Oil level	~		
VIN:	TMBCT61Z2B2131846	Next Service:	174000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:	S SC W	-0	S SC P	-161-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent $R = rust$ $SC W$ $R = rust$						Operation	~		
R = rust PT = paint defect						Noise	~		
C = crack						Clutch			~
P = pin dent						CV joints	~		
* = decals SC 919						Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S SC W S PT D PT W S SC						Performance	~		
Note: come defects & blemiches may not be displayed in the diagram						Hand Brake	~		
body inspection comments						Tyres (lowest observed tread	•	of tyre	es)
Left side spotlight loose Right side sill damaged									mm
	5					Right front		5	mm
						Left rear		3	mm
Conditions During Rody Inspection:						Right rear		4	mm
Conditions During Body Inspection: Dry						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Bonnet stay bracket missing						Suspension performance	~		
Underbody	oxidisation					Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation			
Interior Comments						Electrical / Accessories	•		
Seats Stains on seats						Head lights	~		
						Tail lights	~		
Carpets	Average					Indicators	~		
Panels	Average					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Average					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)		~	
						CD (basic test only)		~	
						Number of keys	1	•	
Road Conditions During Test Drive: Dry						Central locking	· ·		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)	-		~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera			~
	•								-
Inspected by: John Lindsay Date: 25 Oct 2018									

I have read and understood this condition guide.

Name: .....