

Basic Vehicle Condition Guide

Report ID: 17,710,285


Version: 1

Created: 09 Nov 2018

Make: Model: Holden Astra **Body Style:** Hatchback Year: 2004 Registration: CJS674 Reg Expiry: 25 Nov 2019 **Odometer:** WoF Expiry: 22 Feb 2019 335,766 Kms **Good No:** 17710285 VIN: W0L0AHL4845228451 Next Service: 342079 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Both wing mirrors covers missing Left rear hubcap missing •

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Right side wing mirror faulty Underbody oxidisation

Interior Comments		
Seats	stains, hole drivers seat	
Carpets	Average	
Panels	Average	
Dashboard	Average	

General Comments

Steering cover worn and damaged

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

Inspected by: John Lindsay Date: 09 Nov 2018

Name:

	Pass	Fail	N/A		
Engine					
Oil level	×				
Smoke & fumes	×				
Performance	×				
Noise	×				
Cooling System					
Coolant condition	×				
Performance	×				
Radiator / Hoses (visual)	×				
Transmission					
Operation	×				
Noise	×				
Clutch	×				
CV joints	×				
Wheel bearings	×				
Brakes					
Performance	×				
Hand Brake	×				
Tyres (lowest observed tread depth of tyres)					
Left front		5	mm		
Right front		5	mm		
Left rear		4	mm		
Right rear		5	mm		
Spare		Yes			
Suspension					
Suspension performance	×				
Steering performance	×				
Shock absorbers	×				
Air Conditioning / Heater					
Operation	×				
Electrical / Accessories					
Head lights	×				
Tail lights	×				
Indicators	×				
Dashboard warning lights	×				
Wipers (front & rear)	×				
Window winder FL	×				
Window winder FR	×				
Window winder RL	×				
Window winder RR	×				
Rear view mirrors		×			
Radio (basic test only)	×				
CD (basic test only)	×				
Number of keys	1	1	-		
Central locking	×				
Remote locking	×				
Sat. Nav. (basic test only)			×		
Reversing camera			×		

Signature: