

Report ID: 17,710,421 Version: 1 14 Nov 2018 Created:

Make:	Mazda	Model:	Mazda6	Body Style:	Wagon	1 [Pass	Fail	N/A	
Year:	2015	Registration:	JLA64	Reg Expiry:	29 Jan 2019	E	ngine				
WoF Expiry:	30 Oct 2019	Odometer:	111,440 Kms	Good No:	17710421		Oil level	~			
VIN:	JM0GJ103200206184	Next Service:	112000	Service Histor	y: Yes		Smoke & fumes	~			
						iŀ	Performance	~			
	port is not a warranty	eration is made	for age and mileage	Parts have not	been dismantled or		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System					
a full mechan	ical inspection prior to	purchase and tl	his can be arranged fo	or an additional o	harge.	⊢⊢	Coolant condition	~			
						iŀ	Performance	~			
Key:	S SC	-0	SD S		SD	∣⊢	Radiator / Hoses (visual)	~			
S = scratch						┟┝┰	ransmission	•			
D = dent D SC W D D SC W						╟╴	Operation				
R = rust PT = paint defe				\prod	JHIA		Noise	く く			
C = crack					SC	╟╴	Clutch	•		~	
P = pin dent						╎┝	CV joints	~		•	
* = decals	ssc 916			- AL	EIP s	╟┝	Wheel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs SC S P W D						IF	Performance	~			
		Note: con				╎┝	Hand Brake	v v			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram								•	-f +		
Left side sill dented Windecreen stone chin						Tyres (lowest observed tread depth of tyres)				-	
Windscreen stone chip						⊢⊢	Left front	2		mm	
						⊢⊢	Right front	2		mm	
						╎┝	Left rear	2		mm	
Conditions During Body Inspection: Dry						╢┝	Right rear 4			mm	
Under Corriges & Under Depart Increation Comments						୲⊢	pare Yes				
Under Carriage & Under Bonnet Inspection Comments							Suspension				
						⊢⊢	Suspension performance	~			
						⊢⊢	Steering performance	~			
							Shock absorbers	~			
						A	ir Conditioning / Heater				
Interior Commonts							Operation	~			
Interior Comments Hole in passenger seat, stains on seats						E	Electrical / Accessories				
Seats	Hole in pa	ssenger seat,stal	ns on seats				Head lights	~			
Carpote	Average						Tail lights	~			
Carpets						IL	Indicators	~			
Panels	Marks and	scratches on rea	ir panels				Dashboard warning lights	~			
	Scratches	on dashboard					Wipers (front & rear)	~			
Dashboa	ru					[Window winder FL	~			
г Г						ίſ	Window winder FR	~			
General Comments						[Window winder RL	~			
							Window winder RR	~			
							Rear view mirrors	~			
							Radio (basic test only)	~			
							CD (basic test only)	~			
						ןן	Number of keys	2			
Road Conditions During Test Drive: Dry						۱Ľ	Central locking	~			
			•			⊢⊢	Remote locking	~			
Engine Tir	ming Mechanism:	Timing	Chain				Sat. Nav. (basic test only)	~			
Evidence of Cam Belt Replacement: Not Applicable Kms:							Reversing camera	v			
Inspected	Inspected by: John Lindsay Date: 14 Nov 2018										

I have read and understood this condition guide.

Name:

Signature: