

Report ID: 17,712,027 Version: 1 05 Dec 2018 Created:

Signature:

| Make: | Ford | Model: | Mondeo | Body Style: | Wagon | | Pass | Fail | N/A |
|--|--------------------------|-----------------|------------------------|-------------------|----------------------|--|--------------|-----------|----------|
| Year: | 2015 | Registration: | JLZ972 | Reg Expiry: | 23 Feb 2019 | Engine | 1 | | I |
| WoF Expiry: | 16 Nov 2019 | Odometer: | 84,572 Kms | Good No: | 17712027 | Oil level | ~ | | |
| VIN: | WF0FXXWPCFFS2268 | Next Service: | 101409 | Service Histor | y: No | Smoke & fumes | ~ | | |
| | | | | | | Performance | ~ | | |
| | port is not a warranty | aration is made | for ago and milaago | Darts have not | been dismonthed or | Noise | ~ | | |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge. | | | | | | Cooling System | | | |
| a full mechan | ical inspection prior to | purchase and tl | nis can be arranged fo | r an additional c | harge. | Coolant condition | ~ | | |
| | | | | | | Performance | ~ | | |
| Key: | sc | -0 | Р | | Р | Radiator / Hoses (visual) | ~ | | |
| S = scratch | | | | | | | Transmission | | |
| D = dent | sw 6/6 | | | The | EID S | Operation | ~ | | |
| R = rust | | | | 10 | JHIH | Noise | ~ | | |
| PT = paint defects C = crack | | | | + | SC | Clutch | • | | ~ |
| P = pin dent | | | | | | CV joints | ~ | | • |
| * = decals | sc pip | | | AL. | BIR SDW | Wheel bearings | ~ | | |
| SC = stone chips | | | | | | Brakes | | | |
| W = significant scuffs SC W SP P W D | | | | | | Performance | | | |
| | | Nataron | | | | | ~ | | |
| Body Insp | pection Comments | Note: son | ne defects & blemishes | may not be disp | nayed in the diagram | Hand Brake | | <i>с.</i> | <u> </u> |
| Windscreen stone chip | | | | | | Tyres (lowest observed tread depth of tyres) | | | |
| | | | | | | Left front | | 1 | mm |
| | | | | | | Right front | | 5 | mm |
| | | | | | | Left rear | | 7 | mm |
| Conditions During Body Inspection: Dry | | | | | | Right rear | 7 mm | | |
| Under Carriage & Under Bonnet Inspection Comments | | | | | | Spare | Yes | | |
| Under Ca | rriage & Under Bor | inet inspectio | on Comments | | | Suspension | | | |
| | | | | | | Suspension performance | ~ | | |
| | | | | | | Steering performance | ~ | | |
| | | | | | | Shock absorbers | ~ | | |
| | | | | | | Air Conditioning / Heater | | | |
| | | | | | | Operation 🖌 | | | |
| Interior Comments | | | | | | Electrical / Accessories | | | |
| Seats | Average | | | | | Head lights | ~ | | |
| Comoto | Average | | | | | Tail lights | ~ | | |
| Carpets | | | | | | Indicators | ~ | | |
| Panels | Average | | | | | Dashboard warning lights | ~ | | |
| | Average | | | | | Wipers (front & rear) | ~ | | |
| Dashboa | rd | | | | | Window winder FL | ~ | | |
| | | | | | | Window winder FR | ~ | | |
| General C | <u>Comments</u> | | | | | Window winder RL | ~ | | |
| | | | | | | Window winder RR | ~ | | |
| | | | | | | Rear view mirrors | ~ | | |
| | | | | | | Radio (basic test only) | ~ | | |
| | | | | | | CD (basic test only) | ~ | | |
| | | | | | | Number of keys | 2 | L | I |
| Road Conditions During Test Drive: Dry | | | | | | Central locking | ~ | | |
| Road Conditions During Test Drive: Dry | | | | | | Remote locking | ~ | | |
| Engine Timing Mechanism: Timing Chain | | | | | | Sat. Nav. (basic test only) | ~ | | |
| Evidence of Cam Belt Replacement: Not Applicable Kms: | | | | | | Reversing camera | ~ | | |
| | • | | •• | | | | - | | |
| Inspected by: John Lindsay Date: 05 Dec 2018 | | | | | | | | | |

I have read and understood this condition guide.

Name: