

Basic Vehicle Condition Guide

Report ID: 17,713,520


Version: 1

Created: 08 Jan 2019

Make: Model: Mitsubishi L300 **Body Style:** Van Year: 2007 Registration: DWZ981 Reg Expiry: 04 Jan 2019 **Odometer:** WoF Expiry: 10 Nov 2019 129,881 Kms **Good No:** 17713520 VIN: JMAHNP15V7A800782 Next Service: Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Windscreen stone chips Left side sliding window catch missing

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Oil leak

Hole in left side headlight

Interior Comme	<u>ents</u>
Seats	Drivers seat worn, stains on seats
Carpets	Hole in drivers carpet
Panels	Grommet and pocket missing from drivers panel
Dashboard	Average

General Comments

Hard starting Engine belts noisy

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A	
Engine				
Oil level	~			
Smoke & fumes	~			
Performance		~		
Noise		~		
Cooling System				
Coolant condition	~			
Performance	~			
Radiator / Hoses (visual)	V			
Transmission				
Operation	'			
Noise	~			
Clutch	~			
CV joints	VVV			
Wheel bearings	~			
Brakes				
Performance	~			
Hand Brake	~			
Tyres (lowest observed tread depth of tyres)				
Left front	į	5	mm	
Right front	4		mm	
Left rear	(5	mm	
Right rear	(5	mm	
_		Yes		
Suspension				
Suspension performance	~			
Steering performance	~			
Shock absorbers	~			
Air Conditioning / Heater				
Operation			~	
Electrical / Accessories				
Head lights		~		
Tail lights	~			
Indicators	~			
Dashboard warning lights	~			
Wipers (front & rear)	VVV			
Window winder FL	~			
Window winder FR	~			
Window winder RL			~	
Window winder RR			~	
Rear view mirrors	~			
Radio (basic test only)	~			
CD (basic test only)	~			
Number of keys	1	I	I	
Central locking			~	
Remote locking			~	
Sat. Nav. (basic test only)			~	
Reversing camera			~	
Date: 08 Jan 2019				

I have read and understood this condition guide.

Name:

Signature: