

Basic Vehicle Condition Guide

Report ID: 17,713,614

Version:

Engine

Created: 15 Jan 2019

Pass


Fail

N/A

Make: Model: Holden Cruze **Body Style:** Wagon Year: 2013 Registration: HEE125 Reg Expiry: 28 Feb 2019 WoF Expiry: **Odometer:** 22 Nov 2019 161,393 Kms **Good No:** 17713614 VIN: KL3JA35MJEK527472 Next Service: 163000 **Service History:** Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Front spoiler broken

Conditions During Body Inspection: Wet

Under Carriage & Under Bonnet Inspection Comments

One remote not working, the buttons damaged Oil leak

Interior Comments				
Seats	Average			
Carpets	Average			
Panels	Average			
Dashboard	Average			

General Comments

Harsh down change

Inspected by:

Road Conditions During Test Drive: Wet

Engine Timing Mechanism: Cambelt

John Lindsay

Evidence of Cam Belt Replacement: No Kms:

Oil level	~		
Smoke & fumes	~		
Performance	v v		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation		~	
Noise	~		
Clutch			~
CV joints	~		
Wheel bearings	~		
Brakes		•	
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	s)
Left front	3	3	mm
Right front	3		mm
Left rear	6		mm
Right rear	6 r		mm
Spare		Yes	
Suspension			
Suspension performance	>		
Steering performance	~		
Shock absorbers	~		
Air Conditioning / Heater			
Operation	~		
Electrical / Accessories			
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	\(\times \) \(\t		
Wipers (front & rear)	~		
Window winder FL	~		
Window winder FR	~		
Window winder RL	~		
Window winder RR	V		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	2	ı	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			/

I have read and understood this condition guide.

Name:

Signature:

15 Jan 2019

Reversing camera