

Report ID: 17,714,656 Version: 2 14 May 2019 Created:

Make:	Honda	Model:	Insight	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	HAP519	Reg Expiry:	14 Jun 2019	Engine			
WoF Expiry:	08 Feb 2020	Odometer:	71,726 Kms	Good No:	17714656	Oil level	~		
VIN:	7AT08G9MX13201416	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty			-		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:		-0	s s			Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent				1 - L	BID	Operation	~		
R = rust				1 O	JHIN	Noise	~		
PT = paint def C = crack	ect			+		Clutch	V		
P = pin dent	Ho								~
* = decals	sc pp			SI	ANA	CV joints	~		
SC = stone chi	ps US			10	\$P	Wheel bearings	~		
W = significant scuffs SC W						Brakes			
						Performance	~		
Body Insp	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
No cargo blind.					Tyres (lowest observed tread depth of tyres)				
						Left front	1	3	mm
						Right front	4	1	mm
						Left rear	2	2	mm
Conditions During Body Inspection: Wet						Right rear	4 mm		
						Spare	N/A		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Battery pac	k not tested.					Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
<u>General C</u>	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		1
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)	~		
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera		~	
Inspected by: Brian Hill Date: 14 May 2019									

I have read and understood this condition guide.

Name:

Signature: