

Report ID: 17,715,039 Version: 1 15 May 2019 Created:

| Make:  | Audi                     | Model:          | S4                     | Body Style:        | Wagon            |  | Pass      | Fail | N/A  |
|--|--------------------------|-----------------|------------------------|--------------------|------------------|--|-----------|------|--|
| Year:  | 2006                     | Registration:   | JUZ625                 | Reg Expiry:        | 30 Jun 2019      | Engine                                       | I         | 1    | 1  |
| WoF Expiry:  | 02 Jul 2019              | Odometer:       | 116,875 Kms            | Good No:           | 17715039         | Oil level                                    | ~         |      |  |
| VIN:   | WAUZZZ8E46A15202:        | Next Service:   | 122000                 | Service Histor     | <b>y:</b> No     | Smoke & fumes                                | ~         |      | +  |
|  |                          |                 |                        |                    | -                | Performance                                  | -         | ~    | +  |
| Note: This report is not a warranty<br>This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or   |                          |                 |                        |                    |                  | Noise  |           | ~    |  |
| This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends |                          |                 |                        |                    |                  | Cooling System                               |           |      |  |
| a full mechan  | ical inspection prior to | purchase and tl | his can be arranged fo | or an additional o | harge.           | Coolant condition                            | ~         |      | 1  |
|  |                          | _               |                        |                    |                  | Performance                                  | ~         |      | +  |
| Key:   | s w                      | -0              | S                      |                    |                  | Radiator / Hoses (visual)                    | ~         |      | +  |
| S = scratch  |                          |                 |                        |                    |                  | Transmission                                 | •         |      |  |
| D = dent   |                          |                 |                        |                    |                  | Operation                                    | ~         |      | <u> </u>   |
| R = rust<br>PT = paint defect<br>C = crack   |                          |                 |                        |                    |                  | Noise  | ~         |      |  |
|  |                          |                 |                        |                    |                  | Clutch                                       | •         |      | ~  |
| P = pin dent   |                          |                 |                        |                    |                  | CV joints                                    | ~         |      |  |
| * = decals   |                          |                 |                        |                    |                  | Wheel bearings                               | -         |      |  |
| SC = stone chips   |                          |                 |                        |                    |                  | Brakes                                       | ~         |      |  |
| W = significant scuffs   |                          |                 |                        |                    |                  |  |           |      | <u> </u>   |
| Noto: come defecte % blamiches may not be displayed in the diagram   |                          |                 |                        |                    |                  |  | ~         |      |  |
| Body Inspection Comments   |                          |                 |                        |                    |                  | Hand Brake                                   | / /       | of + |  |
| F tow cover missing  |                          |                 |                        |                    |                  | Tyres (lowest observed tread depth of tyres) |           |      |  |
| Sidewall damage LF tyre  |                          |                 |                        |                    |                  | Left front                                   |           |      | mm   |
|  |                          |                 |                        |                    |                  | Right front                                  |           | 5    | mm   |
|  |                          |                 |                        |                    |                  | Left rear                                    |           | 5    | mm   |
| Conditions During Body Inspection: Wet   |                          |                 |                        |                    |                  | Right rear                                   | 4         | 1    | mm   |
| Linder Carriege & Linder Demot Inspection Comments   |                          |                 |                        |                    |                  | · · · · · · · · · · · · · · · · · · ·        | Spare Yes |      |  |
| Under Carriage & Under Bonnet Inspection Comments  |                          |                 |                        |                    |                  | Suspension                                   |           |      | <del>,                                    </del> |
| Noise in pu  | lley area                |                 |                        |                    |                  | Suspension performance                       | ~         |      | <u> </u>   |
|  |                          |                 |                        |                    |                  | Steering performance                         | ~         |      | <u> </u>   |
|  |                          |                 |                        |                    |                  | Shock absorbers                              | ~         |      |  |
|  |                          |                 |                        |                    |                  | Air Conditioning / Heater                    |           |      |  |
| Interior Comments  |                          |                 |                        |                    |                  | Operation                                    | ~         |      |  |
| Interior Comments<br>Good  |                          |                 |                        |                    |                  | Electrical / Accessories                     |           |      |  |
| Seats  | Good                     |                 |                        |                    |                  | Head lights                                  | ~         |      |  |
| Carpets  | Good                     |                 |                        |                    |                  | Tail lights                                  | ~         |      |  |
| Carpets  |                          |                 |                        |                    |                  | Indicators                                   | ~         |      |  |
| Panels   | Good                     |                 |                        |                    |                  | Dashboard warning lights                     | ~         |      |  |
| Dashhaa  | Good                     |                 |                        |                    |                  | Wipers (front & rear)                        | ~         |      |  |
| Dashboa  | iiu                      |                 |                        |                    |                  | Window winder FL                             | ~         |      |  |
|  |                          |                 |                        |                    |                  | Window winder FR                             | ~         |      |  |
| <u>General Comments</u>  |                          |                 |                        |                    | Window winder RL | ~  |           |      |  |
| Engine light on<br>Oil leaks   |                          |                 |                        |                    |                  | Window winder RR                             | ~         |      |  |
|  |                          |                 |                        |                    |                  | Rear view mirrors                            | ~         |      |  |
|  |                          |                 |                        |                    |                  | Radio (basic test only)                      |           | ~    |  |
|  |                          |                 |                        |                    |                  | CD (basic test only)                         |           | ~    |  |
|  |                          |                 |                        |                    |                  | Number of keys                               | 1         |      |  |
| Road Conditions During Test Drive: Wet   |                          |                 |                        |                    |                  | Central locking                              | ~         |      |  |
|  |                          |                 |                        |                    |                  | Remote locking                               |           | ~    |  |
| Engine Timing Mechanism: Timing Chain  |                          |                 |                        |                    |                  | Sat. Nav. (basic test only)                  |           |      | ~  |
| Evidence   | of Cam Belt Replac       | ement: N        | lot Applicable         | Kms:               |                  | Reversing camera                             |           |      | ~  |
|  |                          |                 |                        |                    |                  | L  |           |      |  |
| Inspected by: Stuart Melbourne   |                          |                 |                        |                    |                  | Date: 15 May 20                              | 19        |      |  |
| I have read  | and understood th        | is condition o  | juide. Name: .         |                    |                  | Signature:                                   |           |      |  |