

Basic Vehicle Condition Guide

Report ID: 17,715,209

Pass

Version: 1

Engine

Created: 20 May 2019


Fail

N/A

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2014 Registration: HHJ721 Reg Expiry: 19 Jun 2019 **Odometer:** WoF Expiry: **Good No:** 01 Jun 2019 116,395 Kms 17715209 VIN: MR0EZ12G304157723 Next Service: unknown Service History: Yes

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Detachable tow bar.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy

Interior Comments			
Seats	average, fitted seat covers.		
Carpets	Average		
Panels	Good		
Dashboard	Good		

	_
General	Comments

Tidy 2WD d/cab ute.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Daryll Timms

Evidence of Cam Belt Replacement: No Kms:

Oil level	'		
Smoke & fumes	ν ν		
Performance	~		
Noise	~		
Cooling System		•	
Coolant condition	~		
Performance	<i>v v</i>		
Radiator / Hoses (visual)	~		
Transmission		•	
Operation	~		
Noise	\(\triangle \)		
Clutch	~		
CV joints			~
Wheel bearings	~		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	depth	of tyre	s)
Left front	- 2	2	mm
Right front	2		mm
Left rear	3		mm
Right rear	3 mm		
Spare		Yes	
Suspension			
Suspension performance	~		
Steering performance	\(\triangle \)		
Shock absorbers	~		
Air Conditioning / Heater	,		
Operation	~		
Electrical / Accessories	,		
Head lights	~		
Tail lights	~		
Indicators	~		
Dashboard warning lights	~		
Wipers (front & rear)	~		
Window winder FL	V		
Window winder FR	~		
Window winder RL	\(\triangle \)		
Window winder RR	~		
Rear view mirrors	~		
Radio (basic test only)	~		
CD (basic test only)	~		
Number of keys	3	•	
Central locking	~		
Remote locking	~		
Sat. Nav. (basic test only)			~

I have read and understood this condition guide.

Name:

Signature:

20 May 2019

1

Reversing camera