

Report ID: 17,715,266 Version: 1 16 May 2019 Created:

Make:	Volkswagen	Model:	Passat	Body Style:	Wagon		Pass	Fail	N/A
Year:	2011	Registration:	FZB494	Reg Expiry:	04 Jul 2019	Engine		-	<u> </u>
WoF Expiry:		Odometer:	108,452 Kms	Good No:	17715266	Oil level	~		
VIN:	WVWZZZ3CZBE34115	Next Service:		Service Histor		Smoke & fumes	~		
						Performance	~		-
	port is not a warranty					Noise	~		
	a guide only. Conside sting undertaken. The					Cooling System	•		
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
		_				Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch	Se	0		10/2	X	Transmission	V		
D = dent				1 - L	BID S*	Operation			1
R = rust				10			~		
PT = paint def	ect			$\square \cup$		Noise	~		<u> </u>
C = crack P = pin dent	H		لـــال			Clutch			~
* = decals	sc db				THA	CV joints	~		<b> </b>
SC = stone chi	ps U			10		Wheel bearings	~		
W = significant scuffs						Brakes			
	S			W		Performance	~		<u> </u>
Body Insp	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
R mirror broken						Tyres (lowest observed tread depth of tyres)			
						Left front	5	5	mm
						Right front	e	5	mm
						Left rear	4	ŀ	mm
Conditions During Body Inspection: Wet						Right rear	5 mr		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	1		4
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Good					Tail lights	~		<u> </u>
Carpets	Good					Indicators	~		+
Panels	Good					Dashboard warning lights	~		+
						Wipers (front & rear)	~		
Dashboa	Ird Good					Window winder FL	~		
	I					Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		<u> </u>
						Window winder RL	-		
							<b>v</b>		
						Rear view mirrors	~		──
						Radio (basic test only)	~		──
						CD (basic test only)	~		
						Number of keys	2		T
Road Con	ditions During Test	t Drive:	Wet			Central locking	~		<u> </u>
Engine Ti	ming Machanism	Cambelt				Remote locking	~		<u> </u>
-	ming Mechanism:			<b>V</b> acation		Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~
Inspecte	d by: Stuart Melbourr					Date: 16 May 20	10		
Inspecter						Date. To May 20			

I have read and understood this condition guide.

Name: .....

Signature: .....