

Report ID: 17,715,369 Version: 1 29 May 2019 Created:

Make: Ho	olden	Model:	Epica	Body Style:	Sedan			Pass	Fail	N/A	
Year: 20	007	Registration:	GJC524	Reg Expiry:	02 Jul 2019	En	Engine				
WoF Expiry: 10	0 Mar 2020	Odometer:	153,808 Kms	Good No:	17715369		Dil level	~			
VIN: KL	L3LA69LJ7B084193	Next Service:	168,000kms	Service Histor	<b>y:</b> No	5	Smoke & fumes	~			
						7 6	Performance	~			
	rt is not a warranty auide only. Conside	eration is made	for age and mileage	e. Parts have not	been dismantled or	. 1	Voise	~			
diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.							Cooling System				
a full mechanica	al inspection prior to	purchase and tr	his can be arranged f	or an additional o	inarge.		Coolant condition	~			
	SC W W		P SC S	W	P SC	7 F	Performance	~			
Key:	1.5cm	=		5(0)-		F	Radiator / Hoses (visual)	~			
S = scratch D = dent	TE				商	Tr	ansmission				
R = rust	s sc			210	EIIVs_		Operation	~			
PT = paint defect	NIM				11111		Voise	~			
C = crack							Ilutch			~	
P = pin dent	PSC DR				2414		CV joints	~			
* = decals	THE AL	10		10	SD SD		Wheel bearings	~			
SC = stone chips W = significant scuffs							Brakes				
	S SC W		S SD		S	F	Performance	~			
Body Inspec	ction Comments	Note: som	ne defects & blemishe	es may not be disp	layed in the diagram		land Brake	~			
Fine chips on screen.						Ту	Tyres (lowest observed tread depth of tyres)				
							Left front 3				
						F	Right front	3	3	mm	
							.eft rear	Ľ	5	mm	
Conditions During Body Inspection: Dry						T F	Right rear 5			mm	
							Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Su	Suspension				
OK.						5	Suspension performance	~			
						5	steering performance	~			
						5	shock absorbers	~			
						Ai	Air Conditioning / Heater				
							Operation 🖌				
Interior Comments						Ele	Electrical / Accessories				
Seats	Average					ŀ	lead lights	~			
Carpets	Average						ail lights	~			
							ndicators	~			
Panels	scuffs on c	onsole.					Dashboard warning lights	~			
Dash!	Good					\	Vipers (front & rear)	~			
Dashboard						\	Vindow winder FL	~			
						$\exists \Box$	Vindow winder FR	~			
General Comments						\	Vindow winder RL	~			
Good Epica see	aan.					١	Vindow winder RR	~			
						F	Rear view mirrors	~			
						F	Radio (basic test only)	~			
							CD (basic test only)	~			
							Number of keys 1				
Road Conditions During Test Drive: Dry							Central locking	~			
Г		<b>T'</b>				╡╔	Remote locking	~			
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						5	Sat. Nav. (basic test only)			~	
Evidence of	Cam Belt Replace	ement: N	lot Applicable	Kms:		F	Reversing camera			~	
Inspected b	oy: Daryll Timms						Date: 29 May 20	19			
							Date. 25 May 20	. /			

I have read and understood this condition guide.

Name: .....

Signature: .....