

Report ID: 17,715,428 Version: 4 08 Jul 2019 Created:

Make:	Honda	Model:	Jazz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2005	Registration:	CTA378	Reg Expiry:	20 Jul 2019	Engine			L
WoF Expiry:	29 May 2020	Odometer:	230,082 Kms	Good No:	17715428	Oil level	~		
VIN:	JHMGD38705S204221	Next Service:	240100	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for ago and milaago	Parts have not	been dismonthed or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechar	ical inspection prior to	purchase and t	his can be arranged fo	or an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0		-		Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent R = rust				715		Operation	~		
PT = paint def		FI		$\left(\left \left(\right) \right\rangle \right)$		Noise	~		
C = crack						Clutch			~
P = pin dent	HID				7414	CV joints	~		
* = decals	- Alf			-Jul		Wheel bearings	~		
SC = stone chips						Brakes			<u> </u>
W = significan	t scuffs W					Performance	~		
Body Inc	oction Commonts	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~		
Body Inspection Comments Dent left rear inner wheel arch. Drivers door rubber worn out.						Tyres (lowest observed tread depth of tyres)			L 2S)
						Left front	Left front 4.0		
						Right front	4.	.0	mm
						Left rear	5.	.0	mm
Conditions During Body Inspection: Dry						Right rear	6.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
	, Good					Wipers (front & rear)	~		
Dashboa	rd					Window winder FL	~		
						Window winder FR	~		
General Comments						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	2		
Road Conditions During Test Drive: Dry Central locking							~		
Remote l							~		
Engine Timing Mechanism: Timing Chain Sat. Nav. (basic test only)									~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 16 May 2019									
Inspected by. Drian mini Date: 10 Midy 2019									

I have read and understood this condition guide.

Name:

Signature: