

Report ID: 17,715,854 Version: 2 09 Jul 2019 Created:

Make:	Holden	Model:	Captiva 7	Body Style:	SUV		Pass	Fail	N/A
Year:	2017	Registration:	KYY787	Reg Expiry:	01 Jun 2019	Engine		-	
WoF Expiry:	16 Oct 2019	Odometer:	53,449 Kms	Good No:	17715854	Oil level	~		
VIN:	KL3CD2659JB002032	Next Service:	,	Service Histor		Smoke & fumes	~		
						Performance	~		
	port is not a warranty		6	Danta have a st		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechar	nical inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	SC	-0	P SP	-161-	s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	P SC 6			The	EII SP	Operation	~		
R = rust PT = paint def				\int	JHIH	Noise	~		
C = crack					P	Clutch	•		~
P = pin dent					세비	CV joints	~		
* = decals	s sc 916			-NL	ELLEN	Wheel bearings	~		
SC = stone chips						Brakes			
W = significant scuffs S P SC SC						Performance	~		
		Note: som	ne defects & blemishes	may not be disc	laved in the diagram	Hand Brake	~		
· · ·	pection Comments							of tyre	
Fine chips on front windscreen Front fog lamps not working						Tyres (lowest observed tread depth of tyres) Left front 4			
	g					Right front	4		mm
						Left rear	2		mm
Canalitian	Dunin n De du la s		2			Right rear			mm
Conditions During Body Inspection: Dry									
Under Carriage & Under Bonnet Inspection Comments						Spare Yes Suspension			
4WD						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	V		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats Good						Head lights	~		
						Tail lights	~		
Carpets	Good						~		
Demela	Good					Dashboard warning lights	~		
Panels						Wipers (front & rear)	~		
Dashboa	ard Good					Window winder FL	~		
						Window winder FE	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RE	~		
						Rear view mirrors	~		
						Radio (basic test only)	<i>v</i> <i>v</i>		
						CD (basic test only)			~
						Number of keys	2		_
Pond Conditions During Test Drives						Central locking	2		
Road Conditions During Test Drive: Dry						Remote locking	~		
Francisca Tinzina Machaniana Tinzina Chain							~		
Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
		- · P				Reversing camera	~		
Inspected by: Mathew Varghese Date: 09 Jul 2019									

I have read and understood this condition guide.

Name:

Signature: