



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

|            |             |
|------------|-------------|
| Report ID: | 17,716,436  |
| Version:   | 3           |
| Created:   | 26 Sep 2019 |

|                                    |        |             |                   |
|------------------------------------|--------|-------------|-------------------|
| Make:                              | Nissan | Body Style: | Sedan             |
| Model:                             | Fuga   | VIN:        | 7AT0DH8GX19220972 |
| Year:                              | 2006   | Odometer:   | 66,030 Kms        |
| Road Conditions During Test Drive: | Dry    |             |                   |

| Electrical |                          | 30 | Fuel Flap Release      | ✓                                | Cooling System  |                 | 55  | Coolant Condition   | ✓                      | Exterior  |            | 78                 | Under Carriage              | Good |              |                         |      |          |           |   |
|------------|--------------------------|----|------------------------|----------------------------------|---|-----------------|---|---|------------------------|---|------------|--------------------|-----------------------------|------|--------------|-------------------------|------|----------|-----------|---|
| 1          | Battery                  | ✓  | 31                     | Reversing Camera                 | ✓   | 56              | Performance   | ✓   | 79                     | Sun Roof Operation                                      | •          | 80                 | Front Windscreen (no chips) | Good |              |                         |      |          |           |   |
| 2          | Headlights               | ✓  | 32                     | USB Port                         | •   | 57              | Radiator/Hoses (visual)   | ✓   | 81                     | Back Windscreen (no chips)                              | Good       | 82                 | Side Windows (no chips)     | Good |              |                         |      |          |           |   |
| 3          | Tail Lights              | ✓  | 33                     | Window Lock Switch               | ✓   | Suspension      |   | 58  | Suspension Performance | ✓ <td>83</td> <td>Front Wiper Blades</td> <td>Good</td> | 83         | Front Wiper Blades | Good                        |      |              |                         |      |          |           |   |
| 4          | High Stop Light          | ✓  | Transmission and Drive |                                  | 34  | Operation       | ✓ <td>59</td> <td>Steering Performance</td> <th>✓<td>84</td><td>Rear Wiper Blade</td><td>Good</td></th> | 59  | Steering Performance   | ✓ <td>84</td> <td>Rear Wiper Blade</td> <td>Good</td>   | 84         | Rear Wiper Blade   | Good                        |      |              |                         |      |          |           |   |
| 5          | Front Right Indicators   | ✓  | 35                     | Noise                            | ✓ <td>60</td> <td>Shock Absorbers</td> <th>✓<th colspan="2">Wheels and Tyres</th><td>85</td><td>R/H Mirror</td><td>Good</td></th> | 60              | Shock Absorbers   | ✓ <th colspan="2">Wheels and Tyres</th> <td>85</td> <td>R/H Mirror</td> <td>Good</td> | Wheels and Tyres       |   | 85         | R/H Mirror         | Good                        |      |              |                         |      |          |           |   |
| 6          | Front Left Indicators    | ✓  | 36                     | Clutch                           | •   | 61              | Left Front  | 7   | mm                     | 86  | L/H Mirror | Good               |                             |      |              |                         |      |          |           |   |
| 7          | Rear Right Indicators    | ✓  | 37                     | CV Joints                        | •   | 62              | Right Front   | 7   | mm                     | 87  | L/F Guard  | Good               |                             |      |              |                         |      |          |           |   |
| 8          | Rear Left Indicators     | ✓  | 38                     | Wheel Bearing                    | ✓   | 63              | Left Rear   | 7   | mm                     | 88  | R/F Guard  | Good               |                             |      |              |                         |      |          |           |   |
| 9          | Reversing Lights         | ✓  | 39                     | Wheel Balance                    | ✓   | 64              | Right Rear  | 7   | mm                     | 89  | L/H Doors  | Good               |                             |      |              |                         |      |          |           |   |
| 10         | Rear Reflectors          | ✓  | 40                     | Gearbox (Manual)                 | •   | 65              | Spare   | Yes   | 90                     | R/H Doors   | Good       |                    |                             |      |              |                         |      |          |           |   |
| 11         | Hazard Lights            | ✓  | 41                     | Engine Timing                    | Timing Chain  | 66              | Tools   | ✓   | 91                     | L/H Sill  | Good       |                    |                             |      |              |                         |      |          |           |   |
| 12         | Courtesy Lights          | ✓  | 42                     | Evidence of Cam Belt Replacement | Not Applicable  | Interior        |   | 67  | AC Operation           | ✓   | 92         | R/H Sill           | Good                        |      |              |                         |      |          |           |   |
| 13         | Dashboard Lights         | ✓  | 43                     | Replaced at (odometer reading)   |   | 68              | Heater Fan  | ✓   | 69                     | Seatbelts   | ✓          | 93                 | Boot/Tail Gate              | Good |              |                         |      |          |           |   |
| 14         | Dashboard Dimmer Switch  | ✓  | Brakes                 |                                  | 44  | Front Brakes    | ✓   | 70  | Horn                   | ✓   | 71         | Seat Heaters       | •                           | 94   | Front Bumper | Good                    |      |          |           |   |
| 15         | Number Plate Light       | ✓  | 45                     | Rear Brakes                      | ✓   | 46              | Handbrake   | ✓   | 72                     | Sun Visors  | ✓          | 73                 | Sun Visors Lights/Mirrors   | ✓    | 95           | Rear Bumper             | Good |          |           |   |
| 16         | Dashboard Warning Lights | ✓  | Keys and Locking       |                                  | 47  | Central Locking | ✓   | 74  | Seats                  | Good  | 75         | Carpets            | Good                        | 96   | Roof         | Good                    |      |          |           |   |
| 17         | Speedo                   | ✓  | 48                     | Remote Locking                   | ✓   | 49              | Number of Keys  | 2   | 76                     | Panels  | Good       | 77                 | Dashboard                   | Good | 97           | Bonnet                  | Good |          |           |   |
| 18         | Odometer                 | ✓  | Engine                 |                                  | 50  | Oil Level       | ✓   | 51  | Smokes and Fumes       | ✓   | 52         | Performance        | ✓                           | 53   | Noise        | ✓                       | 98   | Fuel Cap | ✓         |   |
| 19         | Rev Counter              | ✓  | 51                     | Smokes and Fumes                 | ✓   | 52              | Performance   | ✓   | 53                     | Noise   | ✓          | 54                 | Starter Motor               | ✓    | 55           | Reversing Camera        | ✓    | 99       | Mud Flaps | ✓ |
| 20         | Fuel Gauge               | ✓  | 52                     | Performance                      | ✓   | 53              | Noise   | ✓   | 54                     | Starter Motor   | ✓          | 55                 | Reversing Camera            | ✓    | 56           | Performance             | ✓    | 100      | WOF       | ✓ |
| 21         | Wipers Front/Rear        | ✓  | 53                     | Noise                            | ✓   | 54              | Starter Motor   | ✓   | 55                     | Reversing Camera  | ✓          | 56                 | Performance                 | ✓    | 57           | Radiator/Hoses (visual) | ✓    |          |           |   |
| 22         | Window Opener FL         | ✓  | 54                     | Starter Motor                    | ✓   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 23         | Window Opener FR         | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 24         | Window Opener RL         | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 25         | Window Opener RR         | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 26         | Rear View Mirrors        | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 27         | Radio (Basic Test Only)  | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 28         | CD (Basic Test Only)     | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |
| 29         | Boot Open Switch         | ✓  |                        |                                  |   |                 |   |   |                        |   |            |                    |                             |      |              |                         |      |          |           |   |

Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

|               |              |       |             |
|---------------|--------------|-------|-------------|
| Inspected by: | Daryll Timms | Date: | 26 Sep 2019 |
|---------------|--------------|-------|-------------|

**I have read and understood this condition guide:**

|       |  |            |  |
|-------|--|------------|--|
| Name: |  | Signature: |  |
|-------|--|------------|--|