

## **Basic Vehicle Condition Guide**

Report ID: 17,716,525


Version: 1

Created: 24 May 2019

Make: Model: Hyundai **Imax Body Style:** People Mover Year: 2016 Registration: **KBC920** Reg Expiry: 01 Jun 2019 **Odometer:** WoF Expiry: 03 Oct 2019 77,831 Kms **Good No:** 17716525 VIN: KMHWH81RMGU8528 **Next Service:** unknown Service History:

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

Tidy.

Interior Comment	<u>'S</u>
Seats	Good
Carpets	Good
Panels	Good
Dashboard	Good

## **General Comments**

Nice 8 seater people moving van.

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism: Timing Chain** 

**Evidence of Cam Belt Replacement:** Not Applicable Kms:

**Daryll Timms** Inspected by: 24 May 2019

	Pass	Fail	N/A
Engine	-		
Oil level	~		
Smoke & fumes	~		
Performance	\( \times \)		
Noise	~		
Cooling System			
Coolant condition	~		
Performance	~		
Radiator / Hoses (visual)	~		
Transmission			
Operation	~		
Noise	~		
Clutch			~
CV joints			~
Wheel bearings	_		
Brakes			
Performance	~		
Hand Brake	~		
Tyres (lowest observed tread	d depth	of tyre	es)
Left front	1		mm
Right front	7		mm
Left rear	6		mm
Right rear			mm
Spare	<u> </u>	Yes	
Suspension			
Suspension performance	~		
Steering performance	~		
Shock absorbers	V		
Air Conditioning / Heater			
Operation	V		
Electrical / Accessories			
Head lights	·		
Tail lights	<i>'</i>		
Indicators	<i>y</i>		
Dashboard warning lights	1/		
Wipers (front & rear)	\( \times \)		
Window winder FL	V		
Window winder FR	1/		
Window winder RL			./
Window winder RR			1/
Rear view mirrors	~		
Radio (basic test only)	·		
CD (basic test only)	1		
Number of keys	2		
Central locking	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
Domoto lockin		ı	
Remote locking	-		_
Remote locking  Sat. Nav. (basic test only)  Reversing camera			~

I have read and understood this condition guide.

Name:	