

Report ID: 17,716,709 Version: 1 23 May 2019 Created:

Make:	Nissan	Model:	Fuga	Body Style:	Sedan		Pass	Fail	N/A	
Year:	2006	Registration:	MDH479	Reg Expiry:	20 Mar 2020	Engine				
WoF Expiry:	02 Oct 2019	Odometer:	71,763 Kms	Good No:	17716709	Oil level	~			
VIN:	7AT0DH8GX15401743	Next Service:	76500	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty	aration is made	for and milages	Darts have not	been dismonthed or	Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
a full mechan	ical inspection prior to	purchase and the	nis can be arranged fo	or an additional o	harge.	Coolant condition	~			
						Performance	~			
Key:		-0		-161-		Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent	- GIB			The	EIU/	Operation	~			
R = rust PT = paint defe				í In	JHIH	Noise	~			
C = crack						Clutch	•		~	
P = pin dent						CV joints			~	
* = decals	$\square 616$			- AL	EII PR-	Wheel bearings	~		•	
SC = stone chips							Brakes			
W = significant scuffs						Performance	~			
		Note: som	ne defects & blemishes	may not be disr	laved in the diagram	Hand Brake	~			
	pection Comments	1010.3011		indy not be disp	layed in the diagram		-	oftyre))	
Hard to fault						Tyres (lowest observed tread depth of tyres)				
						Left front	6.	-	mm	
						Right front Left rear	6.		mm	
							6.		mm	
Conditions During Body Inspection: Dry						Right rear	6.1 mm			
Under Carriage & Under Bonnet Inspection Comments						Spare Yes				
Clean	inage a onder bor	meenspeede	<u>eominents</u>			Suspension				
Clean						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Comments						Operation 🖌				
Good						Electrical / Accessories				
Seats	0000					Head lights	~			
Carpets	Good					Tail lights	~			
	Good					Indicators	~			
Panels						Dashboard warning lights	~			
Dashboa	rd Good					Wipers (front & rear)	~			
						Window winder FL	~			
Concret	ommonts					Window winder FR	~			
	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Conditions During Test Drive: Dry Central locking							~			
Engine Timing Mechanismu Timing Chain						Remote locking	~			
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			2	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera	~			
Inspected	Inspected by: Stuart Melbourne Date: 23 May 2019									

I have read and understood this condition guide.

Name: