

Pass Fail N/A

Year:	2004	<b>Registration:</b>	MDF150	<b>Reg Expiry:</b>	25 Aug 2019	Engir	ne				
WoF Expiry:	14 Jun 2020	Odometer:	186,103 Kms	Good No:	17716778	Oil	level	~			
VIN:	7AT0H64EX13080201	Next Service:	200000	Service Histor	<b>y:</b> No	Smo	oke & fumes	V			
						Perf	formance	r			
	port is not a warranty a quide only. Conside	eration is made	for age and mileage	. Parts have not	been dismantled or	Noi	se	r			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooli	Cooling System				
						Coc	Coolant condition				
	DW		D SC S D			Per	formance	~			
Key:				5(0)-		Rad	liator / Hoses (visual)	r			
S = scratch D = dent						Trans	Transmission				
R = rust						Ope	eration	~			
PT = paint def	ect NP				ארור	Noi	se	~			
C = crack						Clut	tch			~	
P = pin dent	sc de			$\langle \rangle$	74114	CV j	joints	~			
* = decals		10		To .	ELC -	] Wh	eel bearings	~			
SC = stone chips							Brakes				
W = significant scuffs W SC S W						Per	formance	~			
Redulars a stress of the diagram Note: some defects & blemishes may not be displayed in the diagram						Han	Hand Brake		✓ ✓		
Body Inspection Comments						Tyres	Tyres (lowest observed tread depth of tyres)				
						Left	Left front		2.0 mm		
						Rigl	Right front		2.0 mm		
						Left	Left rear		6.0 mn		
Conditions During Body Inspection: Wet						Rigl	Right rear		6.0 mm		
Conditions During Dody inspection. Wet						Spa	Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Susp	Suspension				
						Sus	pension performance	~			
						Stee	ering performance	~			
						Sho	ock absorbers	~			
						Air C	Air Conditioning / Heater				
						Dpe	Operation 🖌				
Interior Comments						Elect	Electrical / Accessories				
Seats	Seats Average				Hea	ad lights	~				
	Good					Tail	lights	~			
Carpets	Good						icators	~			
Panels	Average					Das	hboard warning lights	~			
	Card					pers (front & rear)	~				
Dashboa	ard Good						ndow winder FL	~			
	1					Win	ndow winder FR	~			
General Comments						ndow winder RL	V				
Tear in seat, middle row right hand side. Wear to drivers seat.							ndow winder RR	~			
							r view mirrors	~			
							lio (basic test only)	-	~		
							(basic test only)		~		
							Number of keys		1		
Road Conditions During Test Drive: Dry						- I	ntral locking	~			
							note locking			~	
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:							Nav. (basic test only)			~	
							versing camera			v	
	-						J			•	
Inspected by: Brian Hill Date: 27 May 2019											

I have read and understood this condition guide.

Name: .....

Signature: .....