

Report ID: 17,717,067 Version: 3 31 Jul 2019 Created:

Make:	BMW	Model:	318Ti	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2003	Registration:	FGQ695	Reg Expiry:	22 Sep 2019	Engine				
WoF Expiry:	03 Jul 2020	Odometer:	100,580 Kms	Good No:	17717067	Oil level	~			
VIN:	WBAAU52000KN4379	Next Service:	108000	Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty a guide only. Conside	eration is made	for age and mileage	Parts have not	been dismantled or	Noise	~			
diagnostic tes	sting undertaken. The	vehicle has beer	driven up to 50km/h	from cold. The	Vendor recommends	Cooling System				
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	or an additional o	harge.	Coolant condition	~			
	SC			W		Performance	~			
Key:	La C	-0				Radiator / Hoses (visual)	~			
S = scratch D = dent						Transmission				
D = dent R = rust				715	HIV	Operation	~			
PT = paint defe		r I		$\left[\left(\right) \right]$		Noise	~			
C = crack						Clutch			~	
P = pin dent	HIP				74114	CV joints			~	
* = decals	- Alt			The second		Wheel bearings	~			
SC = stone chips W = significant scuffs						Brakes				
vv = significant	t scuffs W		S			Performance	~			
Body Incr	pection Comments	Note: som	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake	~			
Body Inspection Comments Stone chips and small cracks front screen.						Tyres (lowest observed tread	depth	of tyre	25)	
Stone chips and small cracks front screen.						Left front	. , ,			
						Right front	4.	0	mm	
						Left rear	6.	0	mm	
Conditions During Body Inspection: Wet						Right rear	6.0 mm		mm	
						Spare	N/A			
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater			1	
						Operation	~			
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	, Good					Wipers (front & rear)	~			
Dashboa	rd					Window winder FL	~			
	· ·					Window winder FR	~			
General C	<u>Comments</u>					Window winder RL			~	
						Window winder RR			~	
						Rear view mirrors	~			
						Radio (basic test only)	~			
						CD (basic test only)	~			
						Number of keys	2			
Road Con	ditions During Test	Drive:	Dry			Central locking	~			
			·			Remote locking	~			
-	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~	
Inspected	Inspected by: Brian Hill Date: 27 May 2019									

I have read and understood this condition guide.

Name:

Signature: