

Report ID: 17,717,203 Version: 3 10 Jun 2019 Created:

Make:	Hyundai	Model:	ТВ	Body Style:	Hatchback		Pass	Fail	N/A	
Year:	2007	Registration:		Reg Expiry:	15 Nov 2019	Engine			L	
WoF Expiry:	08 Aug 2019	Odometer:	65,477 Kms	Good No:	17717203	Oil level	~			
VIN:	KMHBT51DR7U70355	Next Service:		Service Histor	y: No	Smoke & fumes	~			
						Performance	~			
	port is not a warranty		6	Danta harra nat		Noise	~			
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System				
						Coolant condition	~			
						Performance	~			
Key:	S	-0	L SC			Radiator / Hoses (visual)	~			
S = scratch						Transmission				
D = dent				The		Operation	~			
R = rust				10	JHIH	Noise	~			
PT = paint def C = crack	ect III			+		Clutch	~		~	
P = pin dent	Ho				JUII —	CV joints	~			
* = decals	sc pp			S.	Ell'As		-			
SC = stone chips						Wheel bearings	~			
W = significant scuffs W S SC W S						Brakes				
						Performance	~			
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram						Hand Brake		<b>6</b> .	Ļ	
Left mirror and door handles need painting. No parcel shelf.						Tyres (lowest observed tread depth of tyres)				
						Left front	5.0 mm			
						Right front	5.	.0	mm	
						Left rear	4	.0	mm	
Conditions During Body Inspection: Dry						Right rear	4.0 mm		mm	
Linder Corriero & Linder Donnet in a stiller Community						Spare Yes				
Under Carriage & Under Bonnet Inspection Comments						Suspension				
						Suspension performance	~			
						Steering performance	~			
						Shock absorbers	~			
						Air Conditioning / Heater				
Interior Commonte						Operation 🖌				
Interior Comments						Electrical / Accessories				
Seats	Good					Head lights	~			
Carpote	Good					Tail lights	~			
Carpets						Indicators	~			
Panels	Good					Dashboard warning lights	~			
	Good				Wipers (front & rear)	~				
Dashboa	ru					Window winder FL	~			
						Window winder FR	~			
General (	<u>Comments</u>					Window winder RL	~			
						Window winder RR	~			
						Rear view mirrors	~			
						Radio (basic test only)	V			
						CD (basic test only)	V			
						Number of keys	1			
Road Conditions During Test Drive: Dry						Central locking	~			
			-			Remote locking	~			
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~	
Evidence	of Cam Belt Replac	ement: N	lo	Kms:		Reversing camera			~	
ц										
Inspected by: Brian Hill Date: 27 May 2019										
I have read and understood this condition guide. Name:										