



# Turners Certified 100 Point Check

**Notes: This report is not a warranty.**

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. Imported vehicles have undergone compliance by an accredited inspection agency. This vehicle have been test driven up to 50km/h from cold.

|            |             |
|------------|-------------|
| Report ID: | 17,717,290  |
| Version:   | 2           |
| Created:   | 26 Sep 2019 |

|                                    |            |             |                   |
|------------------------------------|------------|-------------|-------------------|
| Make:                              | Volkswagen | Body Style: | Hatchback         |
| Model:                             | Golf       | VIN:        | WVWZZZ1KZ8M272241 |
| Year:                              | 2008       | Odometer:   | 47,883 Kms        |
| Road Conditions During Test Drive: | Dry        |             |                   |

| Electrical |                          | 30 | Fuel Flap Release      | ✓                                | Cooling System |                  | 78                        | Under Carriage         | Good         | <div>Turners Certification Key:</div> <div>✓ = Pass</div> <div>✗ = Fail</div> <div>• = Not applicable for this vehicle</div> |                             |                         |      |            |           |            |      |
|------------|--------------------------|----|------------------------|----------------------------------|----------------|------------------|---------------------------|------------------------|--------------|--|-----------------------------|-------------------------|------|------------|-----------|------------|------|
| 1          | Battery                  | ✓  | 31                     | Reversing Camera                 | •              | 55               | Coolant Condition         | ✓                      | 79           |  | Sun Roof Operation          | •                       |      |            |           |            |      |
| 2          | Headlights               | ✓  | 32                     | USB Port                         | •              | 56               | Performance               | ✓                      | 80           |  | Front Windscreen (no chips) | Good                    |      |            |           |            |      |
| 3          | Tail Lights              | ✓  | 33                     | Window Lock Switch               | ✓              | 57               | Radiator/Hoses (visual)   | ✓                      | 81           |  | Back Windscreen (no chips)  | Good                    |      |            |           |            |      |
| 4          | High Stop Light          | ✓  | Transmission and Drive |                                  | Suspension     |                  | 58                        | Suspension Performance | ✓            |  | 82                          | Side Windows (no chips) | Good |            |           |            |      |
| 5          | Front Right Indicators   | ✓  | 34                     | Operation                        | ✓              | 59               | Steering Performance      | ✓                      | 83           |  | Front Wiper Blades          | Good                    |      |            |           |            |      |
| 6          | Front Left Indicators    | ✓  | 35                     | Noise                            | ✓              | 60               | Shock Absorbers           | ✓                      | 84           |  | Rear Wiper Blade            | Good                    |      |            |           |            |      |
| 7          | Rear Right Indicators    | ✓  | 36                     | Clutch                           | •              | Wheels and Tyres |                           | 61                     | Left Front   |  | 5                           | mm                      | 85   | R/H Mirror | Good      |            |      |
| 8          | Rear Left Indicators     | ✓  | 37                     | CV Joints                        | ✓              | 62               | Right Front               | 5                      | mm           |  | 63                          | Left Rear               | 4    | mm         | 86        | L/H Mirror | Good |
| 9          | Reversing Lights         | ✓  | 38                     | Wheel Bearing                    | ✓              | 64               | Right Rear                | 4                      | mm           |  | 65                          | Spare                   | Yes  | 87         | L/F Guard | Good       |      |
| 10         | Rear Reflectors          | ✓  | 39                     | Wheel Balance                    | ✓              | 66               | Tools                     | ✓                      | 88           | R/F Guard  | Good                        |                         |      |            |           |            |      |
| 11         | Hazard Lights            | ✓  | 40                     | Gearbox (Manual)                 | •              | Interior         |                           | 67                     | AC Operation | ✓  | 89                          | L/H Doors               | Good |            |           |            |      |
| 12         | Courtesy Lights          | ✓  | 41                     | Engine Timing                    | Timing Chain   | 68               | Heater Fan                | ✓                      | 90           | R/H Doors  | Good                        |                         |      |            |           |            |      |
| 13         | Dashboard Lights         | ✓  | 42                     | Evidence of Cam Belt Replacement | Not Applicable | 69               | Seatbelts                 | ✓                      | 91           | L/H Sill   | Good                        |                         |      |            |           |            |      |
| 14         | Dashboard Dimmer Switch  | ✓  | 43                     | Replaced at (odometer reading)   |                | 70               | Horn                      | ✓                      | 92           | R/H Sill   | Good                        |                         |      |            |           |            |      |
| 15         | Number Plate Light       | ✓  | Brakes                 |                                  |                |                  | 71                        | Seat Heaters           | •            | 93   | Boot/Tail Gate              | Good                    |      |            |           |            |      |
| 16         | Dashboard Warning Lights | ✓  | 44                     | Front Brakes                     | ✓              | 72               | Sun Visors                | ✓                      | 94           | Front Bumper   | Good                        |                         |      |            |           |            |      |
| 17         | Speedo                   | ✓  | 45                     | Rear Brakes                      | ✓              | 73               | Sun Visors Lights/Mirrors | ✓                      | 95           | Rear Bumper  | Good                        |                         |      |            |           |            |      |
| 18         | Odometer                 | ✓  | 46                     | Handbrake                        | ✓              | 74               | Seats                     | Good                   | 96           | Roof   | Good                        |                         |      |            |           |            |      |
| 19         | Rev Counter              | ✓  | Keys and Locking       |                                  |                |                  | 75                        | Carpets                | Good         | 97   | Bonnet                      | Good                    |      |            |           |            |      |
| 20         | Fuel Gauge               | ✓  | 47                     | Central Locking                  | ✓              | 76               | Panels                    | Good                   | 98           | Fuel Cap   | ✓                           |                         |      |            |           |            |      |
| 21         | Wipers Front/Rear        | ✓  | 48                     | Remote Locking                   | ✓              | 77               | Dashboard                 | Good                   | 99           | Mud Flaps  | ✓                           |                         |      |            |           |            |      |
| 22         | Window Opener FL         | ✓  | 49                     | Number of Keys                   | 2              |                  |                           |                        | 100          | WOF  | ✓                           |                         |      |            |           |            |      |
| 23         | Window Opener FR         | ✓  | Engine                 |                                  |                |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |
| 24         | Window Opener RL         | ✓  | 50                     | Oil Level                        | ✓              |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |
| 25         | Window Opener RR         | ✓  | 51                     | Smokes and Fumes                 | ✓              |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |
| 26         | Rear View Mirrors        | ✓  | 52                     | Performance                      | ✓              |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |
| 27         | Radio (Basic Test Only)  | ✓  | 53                     | Noise                            | ✓              |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |
| 28         | CD (Basic Test Only)     | ✓  | 54                     | Starter Motor                    | ✓              |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |
| 29         | Boot Open Switch         | ✓  |                        |                                  |                |                  |                           |                        |              |  |                             |                         |      |            |           |            |      |

## Turners Certification Key:

✓ = Pass

✗ = Fail

• = Not applicable for this vehicle

|               |              |       |             |
|---------------|--------------|-------|-------------|
| Inspected by: | Daryll Timms | Date: | 26 Sep 2019 |
|---------------|--------------|-------|-------------|

**I have read and understood this condition guide:**

|       |  |            |  |
|-------|--|------------|--|
| Name: |  | Signature: |  |
|-------|--|------------|--|