Turners

Basic Vehicle Condition Guide

Make:	Subaru	**Model:**	Exiga	**Body Style:**	Wagon
Year:	2008	**Registration:**	KZM229	**Reg Expiry:**	26 Oct 2018
WoF Expiry:	24 May 2020	**Odometer:**	158,430 Kms	**Good No:**	17718777
VIN:	7AT0GF1RX17002225	**Next Service:**	165933	**Service History:**	No

Note: This report is not a warranty
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Key:
S = scratch
D = dent
R = rust
PT = paint defect
C = crack
P = pin dent
* = decals
SC = stone chips
W = significant scuffs

Labels on diagram: S W, S W, S W, W, S D, SC, S, S SC, S, SC, W, W, PT, W, PT

Note: some defects & blemishes may not be displayed in the diagram

Body Inspection Comments
Rear door garnish chrome bubbling.

			Pass	Fail	N/A
Engine					
Oil level			✔		
Smoke & fumes			✔		
Performance			✔		
Noise			✔		
Cooling System					
Coolant condition			✔		
Performance			✔		
Radiator / Hoses (visual)			✔		
Transmission					
Operation			✔		
Noise			✔		
Clutch					✔
CV joints			✔		
Wheel bearings			✔		
Brakes					
Performance			✔		
Hand Brake			✔		
Tyres (lowest observed tread depth of tyres)					
Left front			7.0		mm
Right front			7.0		mm
Left rear			4.0		mm
Right rear			4.0		mm
Spare			Yes		
Suspension					
Suspension performance			✔		
Steering performance			✔		
Shock absorbers			✔		
Air Conditioning / Heater					
Operation			✔		
Electrical / Accessories					
Head lights			✔		
Tail lights			✔		
Indicators			✔		
Dashboard warning lights			✔		
Wipers (front & rear)			✔		
Window winder FL			✔		
Window winder FR			✔		
Window winder RL			✔		
Window winder RR			✔		
Rear view mirrors			✔		
Radio (basic test only)			✔		
CD (basic test only)			✔		
Number of keys			2		
Central locking			✔		
Remote locking			✔		
Sat. Nav. (basic test only)					✔
Reversing camera					✔

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments
OK.

Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Average

General Comments
Nice 7 seater AWD wagon.

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: Yes   Kms: 103,130

Inspected by: Daryll Timms   Date: 07 Jun 2019

I have read and understood this condition guide.   Name: ....   Signature: ....