

Basic Vehicle Condition Guide

Report ID: 17,719,020


Version: 1

05 Jun 2019 Created:

Make: Model: Honda Insight **Body Style:** Hatchback Year: 2010 Registration: JPU41 Reg Expiry: 18 Nov 2019 **WoF Expiry: Odometer:** 11 Apr 2020 93,652 Kms **Good No:** 17719020 VIN: JHMZE2850BS200021 **Next Service:** 105560 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Clean

| Interior Comm | <u>ents</u> |
|---------------|-------------|
| Seats | Good |
| Carpets | Good |
| Panels | Good |
| Dashboard | Good |

General Comments

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Timing Chain

Evidence of Cam Belt Replacement: Not Applicable Kms:

Stuart Melbourne 05 Jun 2019 Inspected by: Date:

Name:

| | Pass | Fail | N/A | | |
|--|----------------------------|------|-----|--|--|
| Engine | | | | | |
| Oil level | ~ | | | | |
| Smoke & fumes | \(\times \) | | | | |
| Performance | ~ | | | | |
| Noise | ~ | | | | |
| Cooling System | | | | | |
| Coolant condition | ~ | | | | |
| Performance | V V | | | | |
| Radiator / Hoses (visual) | ~ | | | | |
| Fransmission | | | | | |
| Operation | ~ | | | | |
| Noise | ~ | | | | |
| Clutch | | | ~ | | |
| CV joints | ~ | | | | |
| Wheel bearings | ~ | | | | |
| Brakes | | • | | | |
| Performance | V | | | | |
| Hand Brake | ~ | | | | |
| Tyres (lowest observed tread depth of tyres) | | | | | |
| Left front | 5 | .9 | mm | | |
| Right front | 6.4 | | mm | | |
| Left rear | 6.4 | | mm | | |
| Right rear | 5.5 | | mm | | |
| Spare | | Yes | | | |
| Suspension | | | | | |
| Suspension performance | ~ | | | | |
| Steering performance | V V | | | | |
| Shock absorbers | ~ | | | | |
| Air Conditioning / Heater | | | | | |
| Operation | ~ | | | | |
| Electrical / Accessories | | | | | |
| Head lights | ~ | | | | |
| Tail lights | ~ | | | | |
| Indicators | ~ | | | | |
| Dashboard warning lights | V V V V V V | | | | |
| Wipers (front & rear) | ~ | | | | |
| Window winder FL | ~ | | | | |
| Window winder FR | ~ | | | | |
| Window winder RL | ~ | | | | |
| Window winder RR | ~ | | | | |
| Rear view mirrors | ~ | | | | |
| Radio (basic test only) | ~ | | | | |
| CD (basic test only) | ~ | | | | |
| Number of keys | 2 | I | 1 | | |
| Central locking | ~ | | | | |
| Remote locking | ~ | | | | |
| Sat. Nav. (basic test only) | | | ~ | | |
| Reversing camera | | | ~ | | |
| | | | | | |

Signature: