


<b>Make:</b>	Honda	<b>Model:</b>	Elysion	<b>Body Style:</b>	SUV
<b>Year:</b>	2006	<b>Registration:</b>	KGR359	<b>Reg Expiry:</b>	19 Jun 2020
<b>WoF Expiry:</b>	19 Dec 2019	<b>Odometer:</b>	148,194 Kms	<b>Good No:</b>	17734245
<b>VIN:</b>	7AT08GBPX16101484	<b>Next Service:</b>		<b>Service History:</b>	No

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

## Key:

S = scratch  
D = dent  
R = rust  
PT = paint defect  
C = crack  
P = pin dent  
\* = decals  
SC = stone chips  
W = significant scuffs



## Body Inspection Comments

Note: some defects & blemishes may not be displayed in the diagram

Damage on rear bumper RHS. Stonechips on windscreen. LF bumper lamp lens cracked. Front bumper not fitting correctly RHS.  
CD player not working. Dash panel is broken. Sunglasses holder in roof not opening. Roof lining coming off at rear. Lid missing RHS of lower dash. Wear on RF seatbelt.

Conditions During Body Inspection: Dry

## Under Carriage & Under Bonnet Inspection Comments

Surface rust by spare wheel cradle release bolt on body.

## Interior Comments

Seats	Average
Carpets	Average
Panels	Average
Dashboard	Poor

## General Comments

Drives ok .

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No Kms:

	Pass	Fail	N/A
<b>Engine</b>			
Oil level	✓		
Smoke & fumes	✓		
Performance	✓		
Noise	✓		
<b>Cooling System</b>			
Coolant condition	✓		
Performance	✓		
Radiator / Hoses (visual)	✓		
<b>Transmission</b>			
Operation	✓		
Noise	✓		
Clutch			✓
CV joints	✓		
Wheel bearings	✓		
<b>Brakes</b>			
Performance	✓		
Hand Brake	✓		
<b>Tyres</b> (lowest observed tread depth of tyres)			
Left front	7	mm	
Right front	2	mm	
Left rear	5	mm	
Right rear	3	mm	
Spare	Yes		
<b>Suspension</b>			
Suspension performance	✓		
Steering performance	✓		
Shock absorbers	✓		
<b>Air Conditioning / Heater</b>			
Operation	✓		
<b>Electrical / Accessories</b>			
Head lights	✓		
Tail lights	✓		
Indicators	✓		
Dashboard warning lights	✓		
Wipers (front & rear)	✓		
Window winder FL	✓		
Window winder FR	✓		
Window winder RL	✓		
Window winder RR	✓		
Rear view mirrors	✓		
Radio (basic test only)	✓		
CD (basic test only)		✓	
Number of keys	2		
Central locking	✓		
Remote locking	✓		
Sat. Nav. (basic test only)			✓
Reversing camera	✓		

Inspected by: Roger King

Date: 06 Aug 2019

I have read and understood this condition guide.

Name: .....

Signature: .....