

Report ID: 17,734,526 Version: 1 10 Sep 2019 Created:

Make:	Ford	Model:	Festiva	Body Style:	Hatchback		Pass	Fail	N/A
Year: 2	2001	Registration:	ZU8404	Reg Expiry:	30 Jan 2020	Engine	I		
	09 Aug 2020	Odometer:	118,327 Kms	Good No:	17734526	Oil level	~		
	KNADB1225Y6401957	Next Service:	125000	Service Histor	y: No	Smoke & fumes	~		1
						Performance	~		1
	ort is not a warranty	untina in mondo	for one and miles as	Danta hava nat	hoon diamonthed or	Noise	~		
diagnostic test	a guide only. Conside ting undertaken. The v	ehicle has beer	n driven up to 50km/h	from cold. The	Vendor recommends	Cooling System	•		<u> </u>
a full mechanic	cal inspection prior to	purchase and th	nis can be arranged fo	r an additional o	harge.	Coolant condition	~		
						Performance	~		
Key:	s sc s	-0	sc sc		sc	Radiator / Hoses (visual)	~		
S = scratch	RE	A U			The second	Transmission	•		<u> </u>
D = dent	s sc			The	EIII S	Operation	~		
R = rust PT = paint defec				\int	JHIH	Noise	~		
C = crack					SC SC	Clutch	~		
P = pin dent						CV joints	~		
* = decals	ssc 916			The	ELTP S	Wheel bearings	~		
SC = stone chips	/	20		1al		Brakes	•		
W = significant s	scuffs SC S	$-\emptyset$	SSC SSC		SC	Performance	~		
		Note: som	ne defects & blemishes	may not be disr		Hand Brake	~		
Body Inspe	ection Comments	10000.3011		indy not be disp	ayea in the diagram	Tyres (lowest observed tread	-	oftyre	
						Left front			
							5		mm
						Right front	5		mm
						Left rear	4 mm		
Conditions During Body Inspection: Wet						Right rear	4 mm		
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
<u>onder edn</u>	nage a onder bon	incempeette	<u>Comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			T
Interior Comments						Operation 🖌			
Δνατασο					Electrical / Accessories				
Seats	riveluge					Head lights	~		
Carpets	Average					Tail lights	~		<u> </u>
	Average					Indicators	~		<u> </u>
Panels	Average					Dashboard warning lights	~		ļ
Dashboard	d Average					Wipers (front & rear)	~		<u> </u>
						Window winder FL	~		<u> </u>
Company						Window winder FR	~		<u> </u>
<u>General Co</u>	omments					Window winder RL	~		<u> </u>
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)			~
						Number of keys	2		
Road Cond	litions During Test	Drive:	Wet			Central locking	~		
	· · · · · ·					Remote locking	~		
-	ning Mechanism:	Cambel				Sat. Nav. (basic test only)			~
Evidence o	of Cam Belt Replace	ement: Y	'es	Kms: 77	,110	Reversing camera			~
Inspected	by: Donovan Matara					Date: 10 Sep 20	10		

I have read and understood this condition guide.

Name:

Signature: