

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.

Cooling System Coolant condition V Performance Key: Radiator / Hoses (visual) V S = scratch Fransmission D = dent S SC Operation V R = rustNoise V PT = paint defect C = crackClutch 1 P = pin dent V CV joints SC * = decals Wheel bearings V SC = stone chips Brakes W = significant scuffs S Performance ~ Note: some defects & blemishes may not be displayed in the diagram Hand Brake V **Body Inspection Comments** Tyres (lowest observed tread depth of tyres) Left front 6 **Right front** 6 Left rear 6 **Right rear** 6 Conditions During Body Inspection: Dry Spare Yes Under Carriage & Under Bonnet Inspection Comments Suspension Tidy Suspension performance V Steering performance V Shock absorbers ~ Air Conditioning / Heater Operation V Interior Comments Electrical / Accessories Good Head lights Seats 1 Tail lights 1 Good Carpets Indicators ~ Good Dashboard warning lights 1 Panels Wipers (front & rear) 1 Good Dashboard Window winder FL V Window winder FR V **General Comments** Window winder RL V Window winder RR V Rear view mirrors ~ Radio (basic test only) V CD (basic test only) V Number of keys 2 V Central locking **Road Conditions During Test Drive:** Dry Remote locking V

Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable

Inspected by: Stuart Melbourne

14 Feb 2019 Date:

Sat. Nav. (basic test only)

Reversing camera

Report ID: 17,739,373 Version: 1 Created: 14 Feb 2019

Pass

~

V

V

~

Engine

Oil level

Noise

Smoke & fumes

Performance

N/A

mm

mm

mm

mm

V

~

Fail

I have read and understood this condition guide.

Name:

Kms:

Signature: