

Report ID: 17,741,272 Version: 1 26 Feb 2019 Created:

Make:	Toyota	Model:	Hiace	Body Style:	Minibus		Pass	Fail	N/A
Year:	2012	Registration:	GPS117	Reg Expiry:	14 Nov 2019	Engine		-	<u> </u>
WoF Expiry:	21 Feb 2020	Odometer:	58,658 Kms	Good No:	17741272	Oil level	~		
VIN:	JTFST22P600015275	Next Service:	,	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		f	Dauta have used	harriellen en ale de se	Noise	V		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	nis can be arranged fo	r an additional c	harge.	Coolant condition	~		
						Performance	~		
Key:		-0	SD SD	-161-	SD	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	- HIE			TIS	HILD	Operation	~		
R = rust PT = paint def				\prod		Noise	~		
C = crack					SC	Clutch			~
P = pin dent	HIC				세비	CV joints	~		-
* = decals	sc 6/6			-No-	AD SD	Wheel bearings	~		
SC = stone chips						Brakes			
W = significan	t scuffs		\square	J VWW		Performance	~		
Deskulas		Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
	pection Comments				, ,	Tyres (lowest observed tread	d depth	of tyre	es)
LR lens cracked 12 seater					Left front 6 mm				
						Right front	7		mm
						Left rear	, ,		mm
Conditions During Rody Inspection: Wat						Right rear	6		mm
Conditions During Body Inspection: Wet						Spare Yes			
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Tidy	-	•				Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater	•		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Good					Head lights	~		
						Tail lights	~		
Carpets	Good					Indicators	~		
Panels	Good					Dashboard warning lights	~		
						Wipers (front & rear)	~		
Dashboa	rd Good					Window winder FL	~		
						Window winder FR	~		<u> </u>
General Comments						Window winder RL			~
						Window winder RR			~
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	V		
						Number of keys	4		L
Road Conditions During Test Drive: Dry						Central locking	~		
Road Conditions During Test Drive: Dry						Remote locking	~		
Engine Timing Mechanism: Cambelt						Sat. Nav. (basic test only)			~
Evidence of Cam Belt Replacement: No Kms:						Reversing camera	~		
L	-					_			<u> </u>
Inspecte	Inspected by: Stuart Melbourne Date: 26 Feb 2019								

I have read and understood this condition guide.

Name:

Signature: