

	Performance	~	
Body Inspection Comments Note: some defects & blemishes may not be displayed in the diagram	m Hand Brake	~	
L/H rear wheel has a broken stud	Tyres (lowest observed tread depth of tyres)		
Unable to open rear hatch	Left front	4	mm
	Right front	4	mm
	Left rear	5	mm
Conditions During Body Inspection: Wet	Right rear	5	mm
	Spare	Yes	
Under Carriage & Under Bonnet Inspection Comments	Suspension	•	
	Suspension performance	~	
	Steering performance	~	
	Shock absorbers	~	
	Air Conditioning / Heater	Air Conditioning / Heater	
	Operation	~	
Interior Comments	Electrical / Accessories	1 1	!
Seats Average	Head lights	~	
Average	Tail lights	~	
Carpets	Indicators	~	
Panels Good	Dashboard warning lights	~	
Good	Wipers (front & rear)	~	
Dashboard	Window winder FL	~	
	Window winder FR	~	
<u>General Comments</u>	Window winder RL	~	
	Window winder RR	~	
	Rear view mirrors	~	
	Radio (basic test only)	~	
	CD (basic test only)	~	
	Number of keys	1	
Road Conditions During Test Drive: Wet	Central locking	~	
-	Remote locking	~	
Engine Timing Mechanism: Timing Chain	Sat. Nav. (basic test only)		~
Evidence of Cam Belt Replacement: Not Applicable Kms:	Reversing camera	~	

I have read and understood this condition guide.

Name:

1

Pass

V

V

V

V

V

V

V

V

V

V

V

26 Feb 2019

Fail

N/A

V