

## **Basic Vehicle Condition Guide**

Report ID: 17,742,853

Pass

Version: 1

**Engine** 

Oil level

Smoke & fumes

Created: 07 Mar 2019


Fail

N/A

Make: Model: Toyota Hilux **Body Style:** Utility Year: 2013 Registration: GSZ390 Reg Expiry: 05 Mar 2019 **Odometer: Good No:** WoF Expiry: 10 Mar 2019 199,903 Kms 17742853 VIN: MR0FZ22G601189075 Next Service: 200,000kms Service History: Yes

## Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



**Body Inspection Comments** 

Detachable tow bar.

**Conditions During Body Inspection:** Dry

**Under Carriage & Under Bonnet Inspection Comments** 

OK.

Interior Comments		
Seats	rip on rear seat.	
Carpets	Average	
Panels	Average	
Dashboard	Average	

## **General Comments**

Good 4WD d/cab ute.

Inspected by:

Road Conditions During Test Drive: Dry

**Engine Timing Mechanism:** Cambelt

**Daryll Timms** 

**Evidence of Cam Belt Replacement:** No Kms:

~		
~		
•		
~		
~		
~		
•	•	•
~		
~		
~		
~		
~		
•	•	
~		
~		
d depth	of tyre	es)
	2	mm
	2	mm
3		mm
2		mm
Yes		
	103	
	103	
·	103	
<i>v</i>	103	
<i>V V</i>	163	
V V	163	
V V		
V V		
V V V V		
V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V		
V V V V		
V V V V V		
V V V V V V		
V V V V V V V		
V V V V V V V		
V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V V V V V V V V V V V V		
V V V V V V V V		
	<b>✓</b> depth	d depth of tyre  2  2  3  2

I have read and understood this condition guide.

Name: .....

Signature: .....

07 Mar 2019

~

Reversing camera