

Report ID: 17,742,922 Version: 2 27 Mar 2019 Created:

Make:	Nissan	Model:	Tiida	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2006	Registration:		Reg Expiry:	15 Jul 2019	Engine			L
WoF Expiry:		Odometer:	123,369 Kms	Good No:	17742922	Oil level	~		
VIN:	7AT0DH78X12096230	Next Service:		Service History	-	Smoke & fumes	~		
					,	Performance	~		
	port is not a warranty		<i>.</i>	-		Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends						Cooling System			
a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Coolant condition			
						Performance	~		
Key:		-0	SP S		s	Radiator / Hoses (visual)	~		
S = scratch						Transmission			
D = dent	S D SC			The	EID /	Operation	~		
R = rust				10	JHIH	Noise	~		
PT = paint def C = crack	ect			+		Clutch	V		~
P = pin dent	Ho	KI			JUII —	CV joints	~		V
* = decals	sc pp			AL-	ENR	Wheel bearings	-		
SC = stone chi	ps US	VA		\sqrt{a}	& <u> </u>		~		
W = significant scuffs S S S S S						Brakes			
		Nata				Performance	~		
Body Ins	pection Comments	Note: son	ne defects & blemishes	s may not be disp	layed in the diagram	Hand Brake		<u> </u>	
						Tyres (lowest observed tread depth of tyres)			
						Left front	6.	-	mm
						Right front	6.	0	mm
						Left rear	5.	5.0 m	
Conditions During Body Inspection: Dry						Right rear	5.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
Dirty						Suspension performance	~		
						Steering performance	~		
						Shock absorbers	~		
						Air Conditioning / Heater			
						Operation 🖌			
Interior Comments						Electrical / Accessories			
Seats	Average					Head lights	~		
Carrasta	Average					Tail lights	~		
Carpets						Indicators	~		
Panels	Average					Dashboard warning lights	~		
	Average					Wipers (front & rear)	~		
Dashboa	ird					Window winder FL	~		
						Window winder FR	~		
General (<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
						Remote locking	~		
Engine Ti	ming Mechanism:	Timing (Chain			Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
L							1		
Inspected by: Stuart Melbourne Date: 07 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: