

Report ID: 17,742,933 Version: 2 07 Mar 2019 Created:

Make:	Toyota	Model:	Vitz	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2008	Registration:	KFW631	Reg Expiry:	06 Jun 2019	Engine	1	l	L
WoF Expiry:	22 Dec 2019	Odometer:	63,422 Kms	Good No:	17742933	Oil level	~		
VIN:	7AT0H63EX16103611	Next Service:	65248	Service Histor	y: No	Smoke & fumes	~		
						Performance	~		
	port is not a warranty	aration is made	for age and mileage	Parts have not	been dismantled or	Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
a full mechan	ical inspection prior to	purchase and th	his can be arranged fo	r an additional c	harge.	Coolant condition	~		
	W					Performance	~		
Key:		-0				Radiator / Hoses (visual)	~		
S = scratch D = dent						Transmission			
B = rust				210	HIV	Operation	~		
PT = paint defe	ect NP				10111	Noise	~		
C = crack					SC	Clutch			~
P = pin dent	sc				24114	CV joints	~		
*= decais						Wheel bearings	~		
SC = stone chips W = significant scuffs						Brakes			
W – significan	SC W					Performance	~		
Body Insr	pection Comments	Note: som	ne defects & blemishes	may not be disp	layed in the diagram	Hand Brake	~		
Minor stone chips front screen.						Tyres (lowest observed tread depth of tyres)			
						Left front	3.0 mm		mm
						Right front	3.	.0	mm
						Left rear	6	.0	mm
Conditions During Body Inspection: Dry						Right rear	7.0 mm		mm
						Spare	Yes		
Under Carriage & Under Bonnet Inspection Comments						Suspension			
						Suspension performance	~		
						Steering performance	~		
Shock absorbers							~		
						Air Conditioning / Heater	-		
						Operation	~		
Interior Comments						Electrical / Accessories			
Seats	Poor					Head lights	~		
Carpote	Good					Tail lights	~		
Carpets						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
Dashboa	ra 🛛					Window winder FL	~		
	-					Window winder FR	~		
<u>General Comments</u>						Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Conditions During Test Drive: Dry						Central locking	~		
Remote le							~		
Engine Timing Mechanism: Timing Chain Evidence of Cam Belt Replacement: Not Applicable Kms:						Sat. Nav. (basic test only)			~
Evidence	oi Cam Beit Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Brian Hill Date: 06 Mar 2019									

I have read and understood this condition guide.

Name:

Signature: