

Report ID: 17,743,099 Version: 1 06 Mar 2019 Created:

Signature: .....

Make:	Mitsubishi	Model:	Lancer	Body Style:	Hatchback		Pass	Fail	N/A
Year:	2010	Registration:	FGR869	Reg Expiry:	29 Mar 2019	Engine			<u> </u>
WoF Expiry:	13 Jul 2019	Odometer:	125,464 Kms	Good No:	17743099	Oil level	~		
VIN:	JMFLNCX4AAU00168(	Next Service:	135000	Service Histor	<b>y:</b> Yes	Smoke & fumes	~		
						Performance	~		
	port is not a warranty		с I I			Noise	~		
This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.						Cooling System			
						Coolant condition			
						Performance	~		
Key:		-0			S D R	Radiator / Hoses (visual)	~		
S = scratch	STE	A CO			T	Transmission	•		
D = dent	SDPT			the	S D PT	Operation	~		
R = rust				1 M	JHIH	Noise	~		
PT = paint defe C = crack				+		Clutch	~		<u> </u>
P = pin dent	Ho					CV joints	~		<u> </u>
* = decals	sc pip			AL-	EIRS	Wheel bearings	~		
SC = stone chi	ps US	VA		A	& <u> </u>	Brakes	V		
W = significant scuffs SD W S S						Performance			<u> </u>
			ne defects & blemishes			Hand Brake	~		<u> </u>
Body Insp	pection Comments	Note: son	le délects & biemisnes	may not be disp	layed in the diagram		~		
						Tyres (lowest observed tread depth of tyres)			
						Left front	3		mm
						Right front		3	mm
						Left rear	6		mm
Conditions During Body Inspection: Dry						Right rear	6 mm		mm
Under Carriage & Under Bonnet Inspection Comments						Spare	Yes		
	mage & onder bor	inet inspectic	<u>n comments</u>			Suspension			
						Suspension performance	~		<u> </u>
						Steering performance	~		<u> </u>
						Shock absorbers	~		
						Air Conditioning / Heater			
Interior Comments						Operation 🖌			
Good						Electrical / Accessories			
Seats	Good					Head lights	~		
Carpets	holes RF					Tail lights	~		
						Indicators	~		
Panels	Good					Dashboard warning lights	~		
Dashboa	rd Good					Wipers (front & rear)	~		
						Window winder FL	~		
						Window winder FR	~		
General C	<u>Comments</u>					Window winder RL	~		
						Window winder RR	~		
						Rear view mirrors	~		
						Radio (basic test only)	~		
						CD (basic test only)	~		
						Number of keys	1		
Road Con	ditions During Test	Drive:	Dry			Central locking	~		
						Remote locking	~		
Engine Timing Mechanism: Timing Chain						Sat. Nav. (basic test only)			~
Evidence	of Cam Belt Replac	ement: N	lot Applicable	Kms:		Reversing camera			~
Inspected by: Stuart Melbourne Date: 06 Mar 2019									

I have read and understood this condition guide.

Name: .....