

Basic Vehicle Condition Guide

Report ID: 17,743,121

Pass

Version: 2

Created: 21 Mar 2019


Fail

N/A

Make: Model: SUV Chevrolet Optra **Body Style:** Year: 2006 Registration: FDC194 Reg Expiry: 13 Aug 2019 WoF Expiry: **Odometer: Good No:** 25 Mar 2019 153,794 Kms 17743121 VIN: KL1NA35ZE5K212396 **Next Service:** 163,000 Service History:

Note: This report is not a warranty

This report is a guide only. Consideration is made for age and mileage. Parts have not been dismantled or diagnostic testing undertaken. The vehicle has been driven up to 50km/h from cold. The Vendor recommends a full mechanical inspection prior to purchase and this can be arranged for an additional charge.



Body Inspection Comments

One number plate light out.

Conditions During Body Inspection: Dry

Under Carriage & Under Bonnet Inspection Comments

Tidy.

| Interior Comments | | | | | |
|-------------------|---------|--|--|--|--|
| Seats | Good | | | | |
| Carpets | Average | | | | |
| Panels | Good | | | | |
| Dashboard | Good | | | | |

| C = = = = = | C = m= m= = m+= |
|-------------|-----------------|
| Generai | Comments |

Good tidy wagon.

Inspected by:

Road Conditions During Test Drive: Dry

Engine Timing Mechanism: Cambelt

Evidence of Cam Belt Replacement: No

Daryll Timms

| Central locking | | V | | | | | |
|-------------------|-----------------------------|---|---|--|--|--|--|
| | Remote locking | ~ | | | | | |
| | Sat. Nav. (basic test only) | | ~ | | | | |
| Kms: | Reversing camera | | ~ | | | | |
| Date: 06 Mar 2019 | | | | | | | |
| ame: Signature: | | | | | | | |

| l | Engine | | | | | | | |
|--------|------------------------------|--------------|---------|----------|--|--|--|--|
| l | Oil level | ~ | | | | | | |
| | Smoke & fumes | ~ | | | | | | |
| 1 | Performance | v | | | | | | |
| ı | Noise | ~ | | | | | | |
| l | Cooling System | | | | | | | |
| | Coolant condition | ~ | | | | | | |
| 1 | Performance | <i>V</i> | | | | | | |
| l | Radiator / Hoses (visual) | ~ | | | | | | |
| 1 | Transmission | | | | | | | |
| 1 | Operation | ~ | | | | | | |
| ı | Noise | ~ | | | | | | |
| ۱ | Clutch | | | ~ | | | | |
| l | CV joints | ~ | | | | | | |
| Į | Wheel bearings | ~ | | | | | | |
| l | Brakes | | | | | | | |
| l | Performance | ~ | | | | | | |
| l | Hand Brake | ~ | | | | | | |
| l | Tyres (lowest observed tread | depth | of tyre | es) | | | | |
| | Left front | 4 | .0 | mm | | | | |
| l | Right front | 4 | .0 | mm | | | | |
| _ | Left rear | 3 | .0 | mm | | | | |
| l | Right rear | 3 | .0 | mm | | | | |
| _] | Spare | | Yes | | | | | |
| l | Suspension | | | | | | | |
| l | Suspension performance | ~ | | | | | | |
| l | Steering performance | ~ | | | | | | |
| l | Shock absorbers | ~ | | | | | | |
| | Air Conditioning / Heater | | 1 | | | | | |
| 1 | Operation | ~ | | | | | | |
| l | Electrical / Accessories | | | | | | | |
| l | Head lights | ~ | | | | | | |
| l | Tail lights | ~ | | | | | | |
| l | Indicators | ~ | | | | | | |
| l | Dashboard warning lights | ~ | | | | | | |
| l | Wipers (front & rear) | \(\times \) | | | | | | |
| | Window winder FL | ~ | | | | | | |
| 1 | Window winder FR | V | | | | | | |
| l | Window winder RL | ' | | | | | | |
| l | Window winder RR | ~ | | | | | | |
| | Rear view mirrors | ~ | | | | | | |
| | Radio (basic test only) | ~ | | | | | | |
| | CD (basic test only) | ~ | | | | | | |
| _ | Number of keys | 2 | | 1 | | | | |
| J | Central locking | ~ | | | | | | |
| 1 | Remote locking | ~ | | | | | | |
| | Sat. Nav. (basic test only) | | | ~ | | | | |
| | Reversing camera | | | ' | | | | |
| | | | | | | | | |

I have read and understood this condition guide.